

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 21 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron USA Inc	API Number 3002524862
Property Name VGSAU	Well No. 44

Surface Location

PL - Loc F	Section 2	Township T19S	Range R34E	Feet From 1330	N/S Line N	Feet From 1330	E/W Line W	County Lea
----------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

YES	TAB WELL NO	YES	SHIFT-IN NO	INJ NO	SWD	OIL	PRODUCER	GAS	DATE 7/27/15
-----	-----------------------	-----	-----------------------	------------------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø	N/A	N/A	Ø	1850
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Ø/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Ø/N	Y/N	Y/N	Ø/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Water flood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Eddy Galle	BS 9/3/2015
Printed name: EDDY GALLE	OIL CONSERVATION DIVISION
Title: SSP	Entered into RBDMS
E-mail Address: eddy@chevron.com	Re-test
Date: 7/29/15	Phone: 575-631-8516
7/27/15	Witness: [Signature]

INSTRUCTIONS ON BACK OF THIS FORM

SEP 03 2015