

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 21 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA Inc	API Number 30025 27974
Property Name VGSAU	Well No. 63

Surface Location

BL - Lot 13	Section 2	Township T8S	Range R37E	Feet from 50	N/S Line N	Feet From 2630	E/W Line E	County LEA
-----------------------	---------------------	------------------------	----------------------	------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR NO	PRODUCER YES	DATE 7/27/2015
-------------------------	----------------------	-----------------------	------------------------	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	ϕ	ϕ	N/A	ϕ	20
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Water flood if applies

OK

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BL 9/13/2015

Signature: Eddie Gallegos	OIL CONSERVATION DIVISION
Printed name: EDDIE GALLEGOS	Entered into RBDMS
Title: SSP5	Re-test
E-mail Address: civ9@chevron.com	
Date: 7/27/15	Phone: 575-631-8516
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 03 2015