

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 21 2015

RECEIVED

BRADENHEAD TEST REPORT

Operation Name CHEVRON	API Number 30025 3021
Property Name VG SAU	Well No. 122

Surface Location

NE 1/4	Section 1	Township T18S	Range R34E	Feet from 1336	N/S Line N	Feet from 660	E/W Line E	County Lea
--------	---------------------	-------------------------	----------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES ☒ NO	SHUT-IN ☒ YES ☒ NO	INJECTOR ☒ YES ☒ NO	SWD ☒ YES ☒ NO	PRODUCER ☒ YES ☒ NO	GAS ☒ YES ☒ NO	DATE 7/28/2015
---	---	--	---	--	---	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	1800
Flow Characteristics					
Puff	Y / X	Y / X	Y / N	Y / N	CO2 X
Steady Flow	Y / X	Y / X	Y / N	Y / N	WTR X
Surges	Y / X	Y / X	Y / N	Y / X	GAS -
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / X	Y / X	Y / N	Y / X	Injected for
Water	Y / X	Y / X	Y / N	Y / X	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Eddy Gallegos	BS 9/3/2015
Printed name: EDDY GALLEGOS	OIL CONSERVATION DIVISION
Title: SSP5	Entered into RBDMS
E-mail Address: e.vga@chevron.com	Re-test
Date: 7/28/15	
Phone: 575 631-8516	
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 03 2015