

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 21 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name	CHEVRON USA Inc	API Number	300253798
Property Name	VG SAU	Well No.	147

Section	2	Township	T18S	Range	R34E	Feet from	1360	N/S Line	N	Feet from	660	E/W Line	E	Corner	LEA
---------	---	----------	------	-------	------	-----------	------	----------	---	-----------	-----	----------	---	--------	-----

Well Status

TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJECTOR	NO	SWD	OIL	PRODUCER	GAS	DATE	7/28/2015
-----------	-----	----	---------	-----	----	----------	----	-----	-----	----------	-----	------	-----------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	30	2000
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 X
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS -
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Csg - 30# gas - down to zero @ 10 sec. gmb.

Signature:	Edythe Gallen	Entered into RBDMS
Printed name:	EDYTHE GALLEN	Re-test
Title:	SSPS	
E-mail Address:	e.ig@Chevron.com	
Date:	7/28/15	
Phone:	575-631-8516	
Witness:	Spencer	

INSTRUCTIONS ON BACK OF THIS FORM