

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 21 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA Inc	API Number 30-025-36683
Property Name VGSALU	Well No. 132

Surface Location

UL - Lot I	Section 2	Township T18S	Range R34E	Feet from 2630	NS Line S	Feet from 660	EW Line E	County Lea
----------------------	---------------------	-------------------------	----------------------	--------------------------	---------------------	-------------------------	---------------------	----------------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJECTOR ☒ YES ☐ NO	SWD ☐ YES ☒ NO	OIL ☐ YES ☒ NO	GAS ☐ YES ☒ NO	DATE 7/28/2015
--	--	---	--	--	--	--------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	Ø	2/A	2/A	Ø	2000
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	OK

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Edye Gallegos	BS 9/13/2015
Printed name: EDYE GALLEGOS	OIL CONSERVATION DIVISION
Title: SSLS	Entered into RBDMS
E-mail Address: eivga@chevron.com	Re-test
Date: 7/28/15	
Phone: 575-631-8516	
Witness: George Brown	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 03 2015