

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 21 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON					API Number 30025 37994				
Property Name VGSAU					Well No. 145				
Surface Location									
UL - Lot F	Section 2	Township T8S	Range R34E	Feet from 1355	N/S Line N	Feet From 1910	E/W Line W	County Lea	
Well Status									
TA'D WELL YES	NO	YES	SHUT-IN NO	INJ NO	INJECTOR NO	SWD	OIL	PRODUCER NO	GAS NO
									DATE 7/28/2015

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	300
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Eddy Gallegos		BS 9/3/2015	
Printed name: EDDY GALLEGOS		OIL CONSERVATION DIVISION	
Title: SSP		Entered into RBDMS	
E-mail Address: eiv9@chevron.com		Re-test	
Date: 7/28/15	Phone: 575-631-8516		
Witness: [Signature]			

INSTRUCTIONS ON BACK OF THIS FORM

SEP 03 2015