SEP 0 9 2015

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

/	Operator Name Lime Rock Resources II-A, L.P.										³ API Number 30-025-34356		
/	Property Name North Vacuum ABO North Unit										^{Well No.} #163 <i>J</i>		
	^{7.} Surface Location												
/	UL - Lot	Section	Township	Range		Feet from	N/S Line Feet From		om	E/W Line	County		
	М	36	16S	34E		660	S	South 660			West	Lea	
	Well Status												
	Well Status - A SHUT-IN			PRODUCING Oil			DATE 08-24-15						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH OBSERVED DATA If bradenhead flowed water, check all of the descriptions that apply:													
Γ			<u>(A)Su</u>	rf-Interm	(B)Interm(1)-	Interm(2)	(C)Interm-Prod			(D)Prod Csng		(E)Tubing	
F	Pressure		0		N/A		N/A			65		110	
F	Flow Charac	<u>cteristics</u>											
F	Puff			Y / <u>N</u>	Y	7 N		Y / N	1		Y7 N	1	

If bradenhead flowed water, check all of the descriptions that apply:

Y / <u>N</u>

Y / <u>N</u>

<u>Y / N</u>

<u>Y / N</u>

Y / <u>N</u>

CLEAD.	EDECH	SALTY	SULFUR	BLACK
ULLAK	FRESH	SALII	SOLICK	DLACK
·····	1			

Y7 N

Y/N

Y / N

Y / N

Y7 N

Remarks:

Steady Flow Surges

Down to nothing

Gas or Oil

Water

Tested by Eddie Elliott 432-413-0429 Reported by Trish Mealand 575-623-8424

Signature:
All 24/2015

Signature:
OIL CONSERVATION DIVISION

Printed name: Trish Mealand
Entered into RBDMS

Title: Production Analyst
Re-test

E-mail Address: pmealand@limerockresources.com
Image: State of the state of t

SEP 2 5 2015

Y/N

Y / N

Y/N

Y/N

Y/N

Y/N

Y / N

Y / N

Y / N

Y/N