Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Hobbs

FORM APPROVED 135 010

| | OMB NO. 1004- | U. |
|---|-------------------|----|
| | Expires: July 31, | 2 |
| 9 | Serial No. | |

| SUNDRY NOTICES AND REPORTS ON WELLS | |
|---|----|
| Do not use this form for proposals to drill or to re-enter an | |
| abandoned well. Use form 3160-3 (APD) for such proposals | ١. |

| SUNDAT | NOTICES AND REPO | HIS ON WE | LLO | | 141411414127300 | | |
|--|--|--|---|--|---------------------------------------|---------------------|-----|
| Do not use the abandoned we | is form for proposals to II. Use form 3160-3 (API | drill or to re- D) for such pi | enter an roposals. | | 6. If Indian, Allottee of | or Tribe Name | |
| SUBMIT IN TRI | PLICATE - Other instruc | ctions on reve | erse side. | | 7. If Unit or CA/Agree | ement, Name and/or | No. |
| Type of Well | ner | | | | 8. Well Name and No. MOOSE'S TOOT | H 29 26 33 FED 1 | н / |
| Name of Operator CHEVRON USA INC | Contact: E-Mail: CHERRER | CINDY H MUI AMURILLO@C | | | 9. API Well No. 30-025-42168 | - | |
| 3a. Address 1616 W.BENDER BLVD HOBBS, NM 88240 | | 3b. Phone No. Ph: 575-263 Fx: 575-263- | (include area cod 3-04310BBS -0445 | SOD | 10. Field and Pool, or WILDCAT;BON | | |
| Location of Well (Footage, Sec., T Sec 29 T26S R33E Mer NMP | | | NOV 0 2 | 2015 | 11. County or Parish, LEA COUNTY, | | |
| 12. CHECK APPI | ROPRIATE BOX(ES) TO |) INDICATE | NATURE OF | NOTICE, RI | EPORT, OR OTHE | R DATA | |
| TYPE OF SUBMISSION | | | ТҮРЕ (| OF ACTION | | | |
| D Notice of Lettert | ☐ Acidize | ☐ Deep | en | □ Product | on (Start/Resume) | ☐ Water Shut- | Off |
| □ Notice of Intent | ☐ Alter Casing | | ure Treat | Reclama | ation | ☐ Well Integri | ty |
| Subsequent Report | ☐ Casing Repair | □ New | Construction | Recomp | lete | Other | |
| ☐ Final Abandonment Notice | ☐ Change Plans | □ Plug | and Abandon | ☐ Tempor | arily Abandon | | |
| | ☐ Convert to Injection | □ Plug | Back | □ Water D | isposal | | |
| determined that the site is ready for fi CHEVRON USA INC HAS CO **AMENDED REPORT** 11/15/14 DRILL 17 1/2 SURFA CEMENTED WITH 965 SACK THROUGHOUT THE JOB, 10 11/21/14 DRILLED 12 1/4 IMT LTC CASING 4834' AND CEN SKS OF 14.8 PPG, 1.33 FT 3 SURFACE .TEST CASING TO 12/12/2014 DRILLED 8 3/4 PR | OMPLETED THE ABOVE ACE HOLE F/135' TO 888 ACE HOLE F/135' TO 888 ACE HOLE F/135' TO 888 ACE HOLE FOR SERVICE TO 4 ACE HOLE TO 4 ACE HOLE TO 4 ACE HOLE TO 4 ACE HOLE TO 5 ACE HOLE TO 6 ACE HOLE TO 6 ACE HOLE TO 7 | B', RAN 13 3/8 T 3/SK YIELD SURFACE . TE 4834', RAN 9 9 5 OF 11.9 PPG JLL RETURNS TEST GOOD. | CASING 48# PREMIUM PL EST CASING 5/8 CASING 4 6, 2.46 FT 3/SI S THROUGHO | LUS CEMENT TO 1200 PSI 0# HCK-55 K YIELD ECC DUT THE JOE | FOR 30 MIN. TEST NOCEM-C LEAD A | ND 445 | |
| I hereby certify that the foregoing is Name(Printed/Typed) CINDY H | Electronic Submission #: For CHE Committed to AFMSS f | VRON USA INC | C, sent to the I by LINDA JIME | Hobbs - | 2015 (P FD FC | OR RECOR | Ē, |
| Signature (Electronic S | Submission) | | Date 06/09/ | 2015 | ⊕CT 29 | 2015 | |
| | THIS SPACE FO | OR FEDERAL | | | | and | |
| 1.0 | | 1, () | | | BUREAU OF LAND | I D OFFICE | |
| Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or equ | | | Title | L. | SANCODAD TIL | LD U Date | |
| which would entitle the applicant to condu | act operations thereon. | 230juni loude | Office | | Ka | 6 | |
| Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent | U.S.C. Section 1212, make it a statements or representations as | crime for any per to any matter wit | son knowingly ar hin its jurisdiction | nd willfully to ma n. | ke to any department or | agency of the Unite | d |

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Additional data for EC transaction #304408 that would not fit on the form

32. Additional remarks, continued

16500' AND CEMENTED WITH 840 SKS OF 11.3 PPG, 2.612 FT 3/SK YEILD VARICEM-PB1 1ST LEAD, 1180 SKS OF 12.5 PPG, 1.83 FT 3/SK YIELD VARICEM-PB2 AND 135 SKS OF 15.0 PPG, 2.61 FT 3/SK YIELD SOLUCEM-H TAIL. LOST PARTIAL RETURNS 374 BBL INTO DISPLACEMENT (TOTAL DISPLACEMENT OF 380.5 BBL). NO CEMENT OR SPACERS TO SURFACE, TAGGED BOTTOM AT 16501' CEMENT JOB ATTACHED

BASIC ENERGY SERVICES



Research & Development Laboratory 110 West County Road 114 MIDLAND, TEXAS 79702 Tel. (432)687-1994 Fax (432) 687-0066

Customer: Chevron

Well Name: Moose's Tooth 29-26-33 1H

County: Eddy
District: Midland

Lab Analyst: Alain

TVD: 5800 ft.

MD: 5800 ft. BHST: 124°F

внст: 110 °F

Test Date: 1/12/2015

Requested By: Erick Stage Number: Squeeze

> Slurry: Lead Blend Type: Field

Slurry Information

Mix Water: 9.60 gal/sk

Density: 12.80 ppg

Yield: 1.83 cuft/sk

Mix Water %: 92.05

Mud Density: 8.34 ppg

| Cement Blend: | S | uper C |
|---------------|----------|-------------|
| | Kol-Seal | 2.00 lb/sk |
| | C-45 | 0.40 % bwo |
| | STE | 5.00 lb/sk |
| | C-44 | 0.20 % bwo |
| | C-12 | 0.40 % bwo |
| | C-43 | 0.500 % bwo |

| Thickening Time @ | | 110° | F |
|-------------------|------|------|----------------|
| Time to Temp | Time | Вс | Final Pressure |
| 66 | 2:48 | 70 | 4000 psi |
| | | | |

| Compressive Strengths @ | Not Requested |
|-------------------------|---------------|
| Time | |
| | |
| | |
| | ·* |
| | |
| | |
| | |

| | | |) | | |
|----|-----|-----|-----|----|----|
| FW | 300 | 200 | 100 | 6 | 3 |
| | 68 | 61 | 50 | 32 | 19 |
| | FW | | | | |

| Comments | The state of the s | | |
|----------|--|--|--|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

BASIC ENERGY SERVICES



Research & Development Laboratory 110 West County Road 114 MIDLAND,TEXAS 79702 Tel. (432)687-1994 Fax (432) 687-0066

Customer: Chevron

Well Name: Moose's Tooth 29-26-33 1H

County: Eddy
District: Midland
Lab Analyst: Alain

TVD: 5800 ft.

MD: 5800 ft. BHST: 124°F

внст: 110 °F

Test Date: 1/12/2015 Requested By: Erick Stage Number: Squeeze

Slurry: Lead
Blend Type: Field

Slurry Information

Mix Water: 9.01 gal/sk
Density: 13.00 ppg

Yield: 1.75 cuft/sk

Mix Water %: 86.41

Mud Density: 8.34 ppg

| Cement Blend: | S | Super C |
|---------------|----------|-------------|
| | Kol-Seal | 2.00 lb/sk |
| | C-45 | 0.40 % bwo |
| | STE | 5.00 lb/sk |
| | C-44 | 0.20 % bwo |
| | C-12 | 0.40 % bwo |
| | C-43 | 0.500 % bwo |

| Thickening Time @ | | 110° | F |
|-------------------|------|------|----------------|
| Time to Temp | Time | Вс | Final Pressure |
| 66 | 2:46 | 70 | 4000 psi |
| | | | |

| Compressive St | rengths @ | 124°F |
|----------------|-----------|-------|
| Time | UCA CS | |
| 8 Hr. | 298 psi | |
| 12 Hr. | 475 psi | |
| 24 Hr. | 923 psi | |
| 50 psi | 6:00 | |
| 500 psi | 13:26 | |

| id Properties | | Rheological d | lata (cF | 2) | | | |
|---------------|----|---------------|----------|-----|----|----|--|
| emperature FL | FW | 300 | 200 | 100 | 6 | 3 | |
| 80°F | | 68 | 61 | 50 | 32 | 19 | |
| | | | | | | | |

| Comments | Part Contract | French Marie |
|----------|---------------|--------------|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

BASIC ENERGY SERVICES



Research & Development Laboratory 110 West County Road 114 MIDLAND,TEXAS 79702 Tel. (432)687-1994 Fax (432) 687-0066

Customer: Chevron
Well Name: Moose's Tooth 29-26-33 1H

County: Eddy
District: Midland
Lab Analyst: Alain

TVD: 5800 ft. MD: 5800 ft. BHST: 124°F

внст: 110 °F

Test Date: 1/12/2015
Requested By: Erick
Stage Number: Squeeze
Slurry: Lead

Blend Type: Field

Slurry Information

Mix Water: 8.47 gal/sk
Density: 13.20 ppg
Yield: 1.68 cuft/sk

Mix Water %: 81.24

Mud Density: 8.34 ppg

| Cement Blend: Super C | Kol-Seal | 2.00 lb/sk | C-45 | 0.40 % bwoc | STE | 5.00 lb/sk | C-44 | 0.20 % bwoc | C-12 | 0.40 % bwoc | C-43 | 0.500 % bwoc | C-43 | 0.500 % bwoc | C-43 | 0.500 % bwoc | C-45 |

| Thickening Time @ | 2 | 110° | F |
|-------------------|------|------|----------------|
| Time to Temp | Time | Вс | Final Pressure |
| 66 | 2:30 | 70 | 4000 psi |
| : | | | |

| Compressive Strengths @ | Not Requested |
|-------------------------|---------------|
| Time | |
| | |
| | |
| | |
| | |
| | |
| | |

| | | Rheological c | lata (CF | 1 | | |
|----|----|---------------|-----------|---------------|-------------------|---------------------|
| FL | FW | 300 | 200 | 100 | 6 | 3 |
| | | 68 | 61 | 50 | 32 | 19 |
| | FL | FL FW | FL FW 300 | FL FW 300 200 | FL FW 300 200 100 | FL FW 300 200 100 6 |

| omments | A CONTRACTOR OF THE PARTY OF TH | |
|---------|--|--|
| | | |
| | | |
| | | |
| * | | |
| | | |
| | | |



Midland Yard #1721 - Phone 432-687-1994 - P.O. Box 10451 Midland, Texas 79702

PRESSURE PUMPING Job Log

| Customer | | CHEVRON | | | Coment Pump No. | 84850 | | Operator TRX No.2 | | 73175 | | |
|----------------------|--------|----------------|------|-----------------|-----------------|----------------|--|-------------------|-----------------|-------|--|--|
| Address | | | | | Ticket # | 1721- | 10032B | Bulk TRK No.: 15 | | | | |
| City, State, Zip: | | | | | | 16 | | SQZ | | | | |
| Service District: | | MIDLAND, TX | | | | PRODUCTION | | | | | | |
| ell Name and No.: | MOOSE | S TOOTH 29-2 | 6-33 | #1 | Well Location | JAL | Count | y: LEA | States | | | |
| Туре | of Cmt | Sacks | | | Additives | | | Truck Loaded On | | | | |
| SUPER | C THIX | 820 | | | THIXOTROPI | С | 15 F | | Front | Back | | |
| CLAS | SC | 127 | | | NEAT | | 18 Fr | | Front | Back | | |
| | | | | | | | | | Front | Back | | |
| Lead | Tail: | Weight #1 Gal. | Yi | eld | Water Re | quirements | CU. FT. | Man | Hours / Personi | nel | | |
| Lea | ad: | | | | | | 820 | Man Hours: | | | | |
| Ta | il: | | | | | | 127 | # of Men on Job: | | | | |
| Time | - | Volume | Pu | mps | Pres | sure(PSI) | Description of Operation and Materials | | | | | |
| (am/pm) | (BPM) | (BBLS) | Т | С | Tubing | Casing | | | | | | |
| 9:56AM | | | | | | | | ARRIVE ON | LOCATION | | | |
| 10:20AM | | | | | | | | JS. | A | | | |
| 10:34AM | | | | | | | RIG UP CREW | | | | | |
| 12:03 PM | | | | | 2000 | | PRESSURE TEST 2000 PSI | | | | | |
| 12:04PM | 1 | 10 | | | | 0-530 | PUMP 10 BBLS MUD FLUSH | | | | | |
| 12:34PM | 3 | 40 | | | | 530-710 | PUMP 40 BBLS FRESH WATER SPACER | | | | | |
| 12:45PM | 3 | 15 | | | | 710-515 | PUMP 15 BBLS FLOW SEAL | | | | | |
| 1249PM | 3 | 10 | | | | 515-490 | PUMP 10 BBLS FRESH WATER | | | | | |
| 12:56PM | 3 | 261 | | | | 710-190 | PUMP 820 SKS | | | | | |
| 2:36PM | | | | | | 190-0 | SHUT DOWN / WASH UP | | | | | |
| 5:50PM | 0.25 | 7 | | | | 90-980 | PUMP 7 BBLS @ 14.8 90-980 PSI | | | | | |
| 6:00PM | | | | | | | | SHUT DOWN | / WASH UP | | | |
| 6:43PM | 0.33 | 0.5 | | | | 0-825 | DIS | PLACE CSG .5 | BBLS 0-825 P | SI | | |
| 6:50PM | | | | | | 825 | CLOSE IN WELL W/ 825 PSI | | | | | |
| 7:00PM | | | | | | | | RIG DOWN | MOVE OUT | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| 9 5/8 # 40 | SHOE | 4833 | | | | | TYPE | T | - | | | |
| 5 1/2#17 | TOC | 5190 | | | New / Used | | Packer | | Depth | | | |
| | | | | | | | Retainer | | Depth | | | |
| | | | | | | | Perfs | | CIBP | 11.5 | | |
| | - | 11 1 | 0 | | | Basic Represe | | VIN | CE SANDOVAD | 1 | | |
| stomer Sign | ature: | Vand 1 | 12 | was | | Basic Signatur | | 1 | / | W/ | | |
| ustonial digitatura. | | 1 | | Date of Service | | 1/10/2015 | | | | | | |