



State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chewon USA						API Number 30-025-36450			
Property Name Trinity Burgos ABO Unit						Well No. 18			
Surface Location									
UL - Lot J	Section 23	Township 12S	Range 38E	Feet from 1650	N/S Line S	Feet From 2200	E/W Line E	County Lea	
Well Status									
YES	TA'D WELL (NO)	YES	SHUT-IN (NO)	(INJ)	INJECTOR SWD	OIL	PRODUCER GAS	DATE 2/25/16	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	Ø	Ø		Ø	346
Flow Characteristics					
Puff	Ø / N	Ø / N	Y / N	Ø / N	CO2 —
Steady Flow	Y / Ø	Y / Ø	Y / N	Y / Ø	WTR ✓
Surges	Y / Ø	Y / Ø	Y / N	Y / Ø	GAS —
Down to nothing	Ø / N	Ø / N	Y / N	Ø / N	Type of Fluid
Gas or Oil	Y / Ø	Y / Ø	Y / N	Y / Ø	Injected for
Water	Y / Ø	Y / Ø	Y / N	Ø / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name: SUSTIN WALK		Entered into RBDMS	
Title: FSA		Re-test	
E-mail Address:			
Date: 2-25-16	Phone: 575 704 6224		
	Witness: Carl Flowers		

In
C.F.

MAR 01 2016