HOBBS OCD

MAR 07 2016

State of New Mexico Energy, Minerals and Natural Resources Department **Oil Conservation Division Hobbs District Office**

RECEIVED

7-16-16

BRADENHEAD TEST REPORT API Number **Operator Name** 30-025-31708 Chevron, U.S.A. INC 1 Well No. Property Name 79 Vacuum Glorieta West Unit 7. Surface Location Feet from N/S Line Feet From E/W Line UL - Lot Section Township Range County 36 w 15 Lea 34E 2561 5 1351 175 Well Status TA'D WELL INJECTOR PRODUCER SHUT-IN DATE TRA 10 SWD OIL GAS YES YES XO

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	()	N/A	N/A	O	1335
Flow Characteristics					
Puff	Y/Ø	Y/N	Y / N	Y/O	$\frac{\text{CO2}}{\text{WTR} \chi}$
Steady Flow	Y/Ø	Y/N	Y/N	Y/Ø	
Surges	Y / 🐼	Y/N	Y / N	Y/O	GAS
Down to nothing	027 N	Y/N	Y/N	00/ N	Injected for
Gas or Oil	Y/O	Y/N	Y / N	¥ / Ø	Waterflood if applies.
Water	Y/Ø	Y/N	Y/N	Y/X	-

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	2	OIL CONSERVATION DIVISION
Printed name: Tanner DeHaan		Entered into RBDMS KH 3-8-16
Title: FSA		Re-test
E-mail Address: TZYR@Chevron.	com	
Date: 2-16-16	Phone: 575-390-4449	
	Witness:	and the second sec

INSTRUCTIONS ON BACK OF THIS FORM