	a strange of the state			OCD-HOBBS					
Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side.				FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMLC061873 6. If Indian, Allottee or Tribe Name					
						7. If Unit or CA/Agre NM709	7. If Unit or CA/Agreement, Name and/or N NM70928x		
						1. Type of Well S Oil Well Gas Well Oth			
				2. Name of Operator DEVON ENERGY PROD CO	LINDA GOOD @dvn.com		9. API Well No. 30-025-42590		
3a. Address 333 WEST SHERIDAN AVE. OKLAHOMA CITY, OK 73102	3b. Phone No. (include area code) Ph: 405-552-6558		10. Field and Pool, or Exploratory PADUCA						
4. Location of Well (Footage, Sec., 7			11. County or Parish, and State						
Sec 7 T25S R32E Mer NMP N	- /		LEA COUNTY, NM						
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NATUR	E OF NOTICE, I	REPORT, OR OTHE	R DATA				
TYPE OF SUBMISSION	TYPE OF ACTION								
Notice of Intent	□ Acidize	Deepen	Produ	ction (Start/Resume)	Water Shut-O				
Subsequent Report	Alter Casing	Fracture Treat	_		□ Well Integrity				
	Casing Repair	New Construc	_	1	Other ShutIn Notice				
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abar Plug Back		orarily Abandon Disposal					
	HOBE	SOCD							
	MAY 1	9 2016							
	DEC	CEIVED CON		SEE ATTACHED FOR					
	REC	EIVED	CON	DITIONS OF A	PPROVAL				
14. I hereby certify that the foregoing is	Electronic Submission #3	338416 verified by the B ERGY PROD CO., L.P.,	LM Well Information	on System					
Name(Printed/Typed) LINDA GC		No. Alle	REGULATORY SE						
Signature (Electronic S	Date (05/05/2016	APPROVED						
	THIS SPACE FO	R FEDERAL OR ST	TATE OFFICE U	SE					
Approved By		Title		MAY 1 1 20	16 Date				
Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu	not warrant or	PRocess							
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a tatements or representations as	crime for any person knowin to any matter within its juris	ngly and willfully to n	Lint is but bet to the little	gen Cof the United				
** OPERAT	OR-SUBMITTED ** O	PERATOR-SUBMIT	TED ** OPERA	TOR-SUBMITTED	**				
		. 1			1				
	mo	6/0CD 5/23/2016							
		5/23/2016							

<u>Conditions of Approval</u> Devon Energy Production Company, L.P. Cotton Draw Unit – 251H, API 3002542590 T25S-R32E, Sec 07, 125FNL & 1650FWL May 11, 2016

This well has been drilled to total depth and has remained uncompleted since 12/25/2015.

This request for Drilling Shut-In status is granted until 12/25/2016.

After this date the DSI status may be extended by submission of a Form 3160-4 Well Completion Report via BLM's Well Information System:

https://www.blm.gov/wispermits/wis/SP

The "as drilled" formation tops, lateral vertical depth, the measured total depth, and bottom hole location are to be listed on that report. Also include the "as drilled" wellbore survey report.

List in the "Additional remarks" box 32 of Form 3160-4 or in box 13 of Form 3160-4 details of justification explaining why the completion is being delayed, and conditions of adequate incentive for the well to be completed.

An inactive/shut-in well bore is a non-producing well that is capable of "beneficial use" i.e. production in paying quantities or of service use. BLM compliance requires an inactive/shut-in well to be restored to use or abandoned; temporarily or permanent.

Extension of the Drilling Shut-In status for more than one year may require a Casing Integrity Test.

- At least 24 hours prior to conducting the Casing Integrity Test, contact the appropriate BLM office. Eddy County call Carlsbad 575-361-2822. Lea County call Hobbs 575-393 3612.
- b. Documentation of a BLM witnessed Casing Integrity Test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 35 to 75 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed CIT. Verify all annular casing vents are plumbed to surface and those valves open to the surface during this pressure test. Pressure leakoff will be evaluated site specifically and affect approvals.
- c. Should the Casing Integrity Test fail or not be conducted submit a procedure for repair, completion, or to plug and abandon the well for BLM approval on or before 12/25/2016.