

Submit 1 Copy To Appropriate District Office	State of New Me	exico	Form C-103
District I – (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-025-23887
District III – (505) 334-6178	1220 South St. Fran	ncis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87		STATE FEE FED 6. State Oil & Gas Lease No.
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Suita i e, i tivi e i	303	6. State Off & Gas Lease No.
87505			
	ICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLU CATION FOR PERMIT" (FORM C-101) FO		NORTH VACUUM ABO WEST UNIT
PROPOSALS.)	_		9 Wall Northern 10
1. Type of Well: Oil Well	Gas Well Other INJECTOR	BES OCD	8. Well Number 18
2. Name of Operator	FIE		9. OGRID Number
CHEVRON USA INC		IN 1 3 2016	4323
3. Address of Operator	ال	JN 1 9 7010	10. Pool name or Wildcat
1616 W. BENDER BLVD HOB			VACUUM; ABO , NORTH
4. Well Location	R	ECEIVED	
Unit LetterF:19	980' feet from the <u>NORTH</u>	line and1980	feet from the <u>WEST</u> line
Section 27	Township 17S Rang	ge 34E	NMPM County LEA
	11. Elevation (Show whether DR,	RKB, RT, GR, etc.)	电影发展的影响和图图图图图
斯里斯里吉拉斯斯斯斯斯里斯斯	4043' GL		
12. Check A	Appropriate Box to Indicate N	ature of Notice, l	Report or Other Data
			•
NOTICE OF IN			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRIL	_
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM		OTLIED. DIATE	
OTHER:	lated operations (Clearly state all	OTHER: RWTP	give pertinent dates, including estimated date
			ppletions: Attach wellbore diagram of
proposed completion or rec		. For Multiple Con	ipietions. Attach wendore diagram of
		THIS WELL HAS	FAILED A MIT TEST. THE PACKER WAS
			E FIND ATTACHED A DETAILED
	ORK DONE ON THIS WELL.		
DI EACE CEE ATTACHEL	ODICIANI MITCHART WEN	OTIFIED MAXEY	BROWN /NMOCD ON MIT TEST.
7	INDEAZE OX) CHART	PACKER FLUID
, 1	NUREN SE		700120
	F TO NOT AL	LOWING	TACKER FLULD
7	EMY. 10 S	TABLE 2	PRIOR TO TEST
			1722
0.15	n: n ! n		MAS.
Spud Date:	Rig Release Da	te:	
I hereby certify that the information	above is true and complete to the be	est of my knowledge	and belief.
A			
SIGNATURE Condy Herrere	Maria PERMITT	DIC ODECLALICT	DATE 06/02/2016
SIGNATURE 4041 WOOD	FITTURE PERMITT	ING SPECIALIST	DATE <u>06/03/2016</u>
Type or print name CINDV HERR	EDA-MUDII I O E-mail address:	Charraramurilla@c	hevron.com PHONE: 575-263-0431
For State Use Only	ERA-WORIEEO E-man address.	Cherreramarmowe	ile violi.com 1110 NE373-203-0431
To State Ost Only		Vino A	
APPROVED BY:	Accepted for Recent	July 1	DATE
Conditions of Approval (if any):	Vecahra		
	MHE 10C	D	
	Thosp	20 11	
	6/13/	D16	
	E1. 2/		







MCBU Completion & WO Report

Report Date: 5/18/2016 50.15% WI, Report #: 6

NORTH VACUUM ABO WEST UNIT 018

Plan Days: 8.00, Tot Days: 3.13 Major Rig Work Over (MRWO) **Last Casing String** SBU Completion Well Category
Comp Well Category 2 Primary Job Type
Casing Repair Original Hole Production Casing Well Type Oil Producer UWDCP-R6144-EXP 17.00 Central Permian Top Depth (MD) (ftKB) Ground Elevation (ft) 4,043.00 Current RKB Elevation 4,058.00, 10/22/2015 th (MD) (ftKB) **PBTD HES Incidents** Caused NPT? 8,781 5/16/2016 Emp. Category Sub-Category Cause Incident Desc меаsurement Method Tagged with 4 3/4" Bit Safety/Inspections AFE Safety Check 06:30 Safety Meeting No incidents, accidents, or environmental issues. Cum To Da 84,706 Tenet of Operations #8 (Adress abnormal conditions) Hazard Wheel #8 (Biological) 0.00 E-Color's: blue/vellow 0.00 Time Log Total Hours (hr) 13.00 Total Tir 75.00 360 My Space DIFO: Keep good communication between rig crew & all BP, keep floor clear of trip hazards and use Personnel/Safety SWA when not sure or in doubt. 13.0 115.50 JSA's Reviewed: Key Well Services, SLB, Peak Cum Pers Tot Hr (hr) 617.75 Completions, Key Energy, Pate Trucking, D&L Meters No Days Since Rec. (days) 7,998 Days Since LTI (days) PTW: None Confined Space:None Safety Check Summary Hot Work: None SSE: None Last Date BOP Drill **Daily Operations BOP Pressure** 5/11/2016 WELL COMPLETED WELL COMPLETED Test Evacuation 5/11/2016 **FINAL REPORT** Fire Drill 5/11/2016 H2S Drill 5/11/2016 JSA TGSM, ZERO PSI CSG & TBG / CONTINUE RIH WITH 2 3/8" IPC PROD TBG LANDING 5 1/2" PACKER From Hobbs, Head west on Hwy 180 (Carlsbad Hwy) ~ 13 miles. Turn right on NM-529, go 2.4 miles, Turn right on to NM 238. Go 7.5 Miles, turn back West towards FMT 5/11/2016 Spill Drill @ 8,511' / PERFORM PRE-MIT TEST "GOOD" / Daily Cost by Tan/Int RELEASE ON-OF TOOL AND CIRCULATE PACKER FLUID THROUGHOUT WELL (200 BBL'S) / LATCH ON, entrance. Drive for about .5 mile and turn left in front of Rot Fld Est (Cost) FMT offices, drive for about 2.2 miles on the dirt road in front of offices heading west, Turn right at yellow cattle 15,556 NDBOP-NUWH / PUMP OUT PLUG RUPTURED 7,200 Tan PREMATURELY BUT WE STILL MANAGED TO CIRCULATE PACKER FLUID AND PERFORM MIT TEST guard and drive for about 2.0 miles and road will take you straight to Key 358 (NVAWU #18) **Daily Contacts** 'GOOD" / RD KEY 358 FROM NVAWU #18 AND PREP Title Drilling Sup't Bohon, (432) 238-TO MOVE IN THE MORNING. David 2322 **Mud Checks** (307) 922-Olree, Kyle Workover Mud/Brine Type Depth (MD) (ftKB) Fluid Type Fluid Density (lb/gal) Com Engineer 3098 (432) 301-Workover Asire, Evan **Time Log** Engineer 2067 UE Re Start Time Dur (hr) Workover (970) 549-Spence. NO OPERATIONS TAKING PLACE AT THIS TIME. INACTIVE Reilly Engineer 6417 PRODCSG CREW TRAVEL TO LOCATION FROM HOBBS RIG (432) 687 Technical Jimenez. CSGREPAIR YARD Assistant 7378 5/11/2016 12:30 Cruz. Jose Well Site (575) 942-JSA TGSM / REVIEWED JSA WITH CREW 06:30 HESMTG Manager 0775 CSGREPAIR MEMBERS AND ALL BP DISCUSSING TODAY'S Well Site (575) 390-Garcia. PROJECTED OPERATIONS / COMMUNICATED E-COLORS, SWA, SWP, TENET OF THE DAY AND HAZARD WHEEL / HAZARDS WERE IDENTIFIED 5/11/2016 12:30 Manager Gabriel 7220 HES Cook, Todd (432) 661-Specialis 8113 AND RECOMMENDED SAFE PROCEDURES WERE GIVEN. (575) 631 Anaya, Luis 8756 PRODCSG, CSGREPAIR PERFORMED RIG WALK AROUND, FILLED OUT BOP ACCUMULATOR CHECK LIST, CALIPER (575) 390-Lopez. 5/11/2016 12:30 OUR 2 3/8" TBG ELEVATORS. Johnny 4093 Personnel PRODCSG, CSGREPAIR. 07:15 CHECK PRESSURE ON WELL-ZERO PSI TBG Total AND ZERO PSI CSG, OPEN WELL. Headcoun Shift Duration (hr) 13.00 5/11/2016 12:30 Chevron PRODUSG TBGP/U CONTINUE RIG WITH 2 3/8" J55 IPC TK99 **Key Well Services** 13.00 CSGREPAIR INJECTION JTS (TOTAL 261 JTS) AND 5 1/2" 13.00 5/11/2016 12:30 NICKEL PLATED INJECTION PACKER WITH 1.43 Smith Services Drilco F PROFILE NIPPLE 1.00 Key Energy Services SPACED OUT AND SET 5 1/2" INJECTION PKRSTRL 11.00 Peak Oilfield Services CSGREPAIR PACKER @ 8,511' 1.50 D & L Meter & Instrument 5/11/2016 12:30 Pate Trucking 8.00 09:15 PKRTST LOAD BACKSIDE AND PRESSURE TEST CSG-1.00 Key Energy Services PACKER TO 540 PSI FOR 30 MINUTES / GAINED 40 PSI IN 30 MINUTES / BLED OFF PRESSURE CSGREPAIR 2.00 5/11/2016 12:30 **Key Well Services** Diesel Usage AND TRAPPED AIR FROM WELL Supply Item Des Consumed Cum Consumed 175.0

Vell Name	JM ABO WEST UNIT	Lease	Field Name	Business Unit
NORTH VACUU		North Vacuum Abo West Unit	Vacuum North	Mid-Continent
ounty/ Parish	State/Province	Original Spud Date	Surface UWI	Surface ChevNo
ea	New Mexico	9/16/1971	3002523887	FG9081
ig/Unit Contractor		Rig/Unit # / Name 358	Rig/Unit Start Date 5/11/2016 08:30	Rig/Unit End Date 5/18/2016 18:30



MCBU Completion & WO Report

Report Date: 5/18/2016 50.15% WI, Report #: 6

Plan Days: 8.00, Tot Days: 3.13

NORTH VACUUM ABO WEST UNIT 018

UE Time UE F
(III) NS
Com TS RIH
S 2 3/8" IPC SENT IN FOR IT TO 1788 YARD
Top Thread
Top Thread
vn Pressure (psi)
Top Depth (ftKB)