

AUG 08 2016

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE CORPORATION	API Number #30-025-33541
Property Name WARN St. A/C 2	Well No. 26

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
E	6	18S	35E	2180'	FNL	400'	FWL	LeA


Well Status

TA'D WELL <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	SHUT-IN <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	INJ <input checked="" type="checkbox"/> INJ <input type="checkbox"/> SWD	PRODUCER <input checked="" type="checkbox"/> OIL <input type="checkbox"/> GAS	DATE 7/29/16
--	--	---	--	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	-	22	30
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 <input type="checkbox"/>
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR <input type="checkbox"/>
Surges	Y/N	Y/N	Y/N	Y/N	GAS <input type="checkbox"/>
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	OIL CONSERVATION DIVISION
Printed name: Albert DeLa Cruz	Entered into RBDMS
Title: Pumper	Re-test
E-mail Address: albert.deLacruz@ApacheCorp.com	
Date: 7/29/16	
Phone:	
Witness: JBow	