Submit One Copy To Appropriate District State of New Mexico	Form C-103
Office District I 1625 N. French Dr., Hobbs, NM 88240 District II	Revised November 3, 2011 WELL API NO.
District II 811 S. First St., Artesia, NM 88210 OIL SONSERVATION DIVISION	30-025-28386
District III 1220 South St. Francis Dr	5. Indicate Type of Lease STATE FEE /
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	B-9505
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	New Mexico AT State
PROPOSALS.) 1. Type of Well: ⊠Oil Well ☐ Gas Well ☐ Other	8. Well Number 12
2. Name of Operator	9. OGRID Number
CrownQuest Operating 3. Address of Operator	213190 10. Pool name or Wildcat
PO Box 53310, Midland, TX 79710	Saunders Permo Upper Penn
4. Well Location	-
Unit Letter <u>G</u> : <u>1980</u> feet from the <u>N</u> line and <u>1650</u> feet from the <u>E</u> line	
Section 15 Township 14S Range 33E NMPM	County <u>Lea</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4200' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JOB	
	pm /
OTHER:	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
☐ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE TITLE Lease Man	DATEDATE
TYPE OR PRINT NAME Saul Leyva E-MAIL: sleyva@crown	quest.com PHONE: 432-559-9066
For State Use Only	
APPROVED BY: Wash Window TITLE P.E.S.	DATE 04/26/2017