Submit One Copy To Appropriate District Office	State of New Mexico			Form C-103		
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			Revised November 3, 2011 WELL API NO.		
District II	OIL CONSERVATION DIVISION			30-025-30024		
811 S. First St., Artesia, NM 88210 District III	1220 South St. Francis Dr.			5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			STATE FEE 6. State Oil & Gas Lease No.		-
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	,			V0-1792-2		
	ES AND REPORTS ON	WELLS		7. Lease Name	or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				State 16		
PROPOSALS.)				8. Well Number 1		
1. Type of Well: Oil Well	Gas Well Other					
2. Name of Operator Mewbourne Oil Company				9. OGRID Number 14744		
3. Address of Operator				10. Pool name or Wildcat		
PO Box 5270, Hobbs, NM 88241				Vacuum, Atoka Morrow North (Gas)		
4. Well Location						-
Unit Letter L: 1980 f	eet from the South line	and 660	feet from the West	line		
Section 16 Township 1						
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
	3966' GL				1000 TO THE TOTAL	
12. Check Appropriate Box to I	ndicate Nature of No	tice, R	eport or Other D	ata		
NOTICE OF INT	ENTION TO:		SHE	SECLIENT DE	EDORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				SEQUENT REPORT OF: K □ ALTERING CASING □		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR				P AND A		
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT	JOB 🗆	0.4	. /
07.175			57	- 1 (- 00D !	•	/
OTHER:						
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.						
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the						
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and						
other production equipment.						
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with						
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed						
from lease and well location.						
All metal bolts and other materials	have been removed. Po	rtable ba	ses have been remo	ved. (Poured onsit	te concrete bases do not hav	/e
to be removed.)	have been addressed as	nor OCD	rulas			
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 						
retrieved flow lines and pipelines.	a woward and wood was					
☑ If this is a one-well lease or last re		ll electri	cal service poles and	d lines have been	removed from lease and we	:11
location, except for utility's distribution	n infrastructure.					
When all work has been completed, re	turn this form to the appr	opriate I	District office to sch	edule an inspectio	en.	
1 1		-				
SIGNATURE 3 Thomas	as T	ITLEH	Environmental Rep_	I	DATE 04/20/2017	
TYPE OR PRINT NAME _ Zack Tho	omas F	-MAII.	zthomas@mewbou	rne.com	PHONE: _575-393-5905	
For State Use Only		ATAL BELL!				
N. 11	4:11	-	P.E.S.		DATE 04/26/20	7/7
APPROVED BY:	Topo T	ITLE	, L.J.		DATE OTICIO CO	")
Conditions of Approval (if any):						