Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240  District II – (575) 748-1283	WELL API NO. 30-025-31930
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	STATE S FEE
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	NEW MEXICO 'R' STATE NCT-3
1. Type of Well: Oil Well Gas Well Other	8. Well Number 25
2. Name of Operator CHEVRON U.S.A. INC.	9. OGRID Number 4323
3. Address of Operator	10. Pool name or Wildcat
6301 DEAUVILLE BLVD, MIDLAND, TX 79706	VACUUM DRINKARD
4. Well Location	
	d660feet from theEASTline /
Section 1 Township 18-S Range	34-E NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,984' (GL)	
3,204 (GL)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL W	
	DRILLING OPNS. P AND A
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEN	IENT JOB
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
The well is currently down due to a suspected casing leak. Water production increased dramatically and the well had a high fluid level. A chlorides test was performed on the produced water which tested close to water from the Blinebry formation. The proposed operations are	
to pull all equipment and to test and identify the casing leak interval. Once the casing leak interval is isolated the cement volumes and	
slurry design will be determined based on the characteristics of the casing leak and we will perform a cement squeeze. Pending a	
successful squeeze the well will be returned to production in the Drinkard.	
Proposed WBD is below.	
Spud Date: Rig Release Date:	
Spud Date.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE TITLE Production Engineer DATE 5/1/17	
Type or print name Michael Stewart E-mail address:michael.stewart@chevron.com PHONE: 432-687-7431	
For State Use Only	
APPROVED BY: May Drawn title AD/II DATE 5/4/2017	
Conditions of Approval (if any):	

## **PROPOSED** WELLBORE DIAGRAM

3/4/2003

Created:

By: SMG By: MAS 5/1/2017 By: MAS New Mexico R State NCT-3 Updated: Field: Vacuum Drinkard

1 TSHP/Range: 18S-34E Well No.: Lease: 25 1980' FSL & 660' FEL Unit Ltr: Surface Location: TSHP/Range: Same Unit Ltr: Sec: **Bottomhole Location:** B-1306-2 API: 30-025-31930 Cost Center: BCT494700 County: Lea NM St Lease: Active Oil Well 3984' GR **Current Status:** Bevation: Directions to Wellsite: Buckeye, New Mexico 3998' KB: Surface Csg. 11 3/4" DF: 3997' Size: Wt.: 42# GL: 3984' Original Spud Date: 4/1/1993 Set @: 1470' 1090 Original Compl. Date: 4/29/1993 Sxs cmt: Yes, circ 300 sxs Circ: TOC 14 3/4" Hole Size: Production Csg. 5 1/2" Size: 17# & 15.5# Wt.: Set @: 8000' 1990 Sxs cmt: Circ: Yes, circ 10 sxs TOC: 11" & 7 7/8" Hole Size: PBTD: 7950' 8000' TD: 7765'-7774' Perforations: 7810'-7850' 7902'-7906' (2 JSPF, 106 holes) Sqz Csg Leak Suspected in Blinebry Possible Interval: 6,315-7,536' TAC @ 7425' 2-7/8" Tbg 0-7836' TD: 8000'