Submit One Copy To Appropriate District Office State of New Mexico	Form C-103
District I District I	Resources Revised November 3, 2011 WELL API NO.
District II 811 S. First St., Artesia, NM 88210 District III 1220 South St. Francis	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis	Dr. STATE X FEE \(\triangle \)
District IV District IV	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAD DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUPROPOSALS.)	THICHEOD IS DITTIE COM
1. Type of Well: X Oil Well Gas Well Other	8. Well Number 601H
2. Name of Operator EOG RESOURCES, INC	9. OGRID Number 7377
3. Address of Operator	10. Pool name or Wildcat
PO BOX 2267 MIDLAND, TEXAS 79702	RED HILLS; UPPER BONE SPRING SHALE
4. Well Location	
Unit Letter A: 220 feet from the NORTH line and 380 feet from the EAST line	
Section 16 Township 26S Range 34E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3312' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON	
PULL OR ALTER CASING MULTIPLE COMPL CA	SING/CEMENT JOB
OTHER.	Leastion is ready for OCD inspection of the BSA
OTHER: Description Descri	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
V. Maydas	
SIGNATURE TITLE: REGU	JLATORY SPECIALIST DATE 11/17/2017
TYPE OR PRINT NAME: KAY MADDOX E-MAIL: <u>kay_maddox@eogresources.com</u> PHONE: _432-686-3658	
For State Use Only	
APPROVED BY: Made 6 A Statem TITLE P.E	.S. DATE 11-22-2017
APPROVED BY: TITLE TITLE TITLE TO THE Conditions of Approval (if any):	DATE