

FLARE INSPECTION

Centennial Resources

LEASE OR FACILITY NAME *Merchant Gap 25 ST. Com*

WELL # *1 H* API# 30- *045* - *41450*

U.L. *M* SEC *25* T *22s* R *34E*

FOOTAGE *40* N *(S)* *350* E *(W)*

IS A FLARE STACK PRESENT? ☒ YES ☐ NO

IS FLARE ACTIVE? ☐ YES ☒ NO

IS GAS TO FLARE METERED? ☒ YES ☐ NO

AREA AROUND FLARE CLEARED? ☒ YES ☐ NO

ENVIRONMENTAL CONCERNS *Gas going to sales*
2 flares on 2 batt. both for tank
vapors.

IS VRU PRESENT? ☐ YES ☒ NO

IS VRU ACTIVE? ☐ YES ☐ NO

COMMENTS

INSPECTOR *Dave Robinson* DATE *1-16-18*