



## FLARE INSPECTION

COG → Batt. is East of this Well  
LEASE OR FACILITY NAME: Jaguar 18 ST.

WELL # 3H API # 30- 025 - 41429

U.L. 0 SEC 18 T 23s R 33e

FOOTAGE 330 NYS 2265 (E)/W

IS A FLARE STACK PRESENT? (YES) NO

IS FLARE ACTIVE? YES (NO)

IS GAS TO FLARE METERED? (YES) NO

AREA AROUND FLARE CLEARED? (YES) NO

COMMENTS: Prod gas is going to sales

IS VRU PRESENT? YES (NO)

IS VRU ACTIVE? YES NO

COMMENTS: Has combustion on tank vapors

INSPECTOR Guy Robinson DATE 1-24-18