

HOBBS OCD

JAN 23 2018

RECEIVED

FLARE INSPECTION

*Murchison*

LEASE OR FACILITY NAME Tackson

WELL # 18H API# 30-625 - 40974

U.L. N SEC 21 T 24S R 33E

FOOTAGE 200 N (S) 770 E (W)

IS A FLARE STACK PRESENT? (YES) NO

IS FLARE ACTIVE? YES (NO)

IS GAS TO FLARE METERED? (YES) NO

AREA AROUND FLARE CLEARED? (YES) NO

ENVIRONMENTAL CONCERNS Lud gas going to sales via  
compressor

IS VRU PRESENT? YES (NO)

IS VRU ACTIVE? YES NO

COMMENTS Compressor used on tank vapors

INSPECTOR Gary Robinson DATE 1-23-18