

HOBBS OCD

JAN 23 2018

RECEIVED

FLARE INSPECTION

*Murchison*

LEASE OR FACILITY NAME *Mogi 9-5T com*

WELL # *#2H* API# 30- *025* - *40976*

U.L. *0* SEC *9* T *24s* R *33E*

FOOTAGE *200* N *(S)* *1980* *(E)* / W

IS A FLARE STACK PRESENT? *(YES)* NO

IS FLARE ACTIVE? YES *(NO)*

IS GAS TO FLARE METERED? *(YES)* NO

AREA AROUND FLARE CLEARED? *(YES)* NO

ENVIRONMENTAL CONCERNS *Lud gas going to sales via Comp.*

IS VRU PRESENT? YES *(NO)*

IS VRU ACTIVE? YES NO

COMMENTS *Combustor used on tank vapors*

INSPECTOR *Gary Robinson* DATE *1-23-18*