



## FLARE INSPECTION

MANZANO

LEASE OR FACILITY NAME: Sodbuster 21 Fee

WELL # 4H API # 30- 025 - 43704

U.L. N SEC 21 T 9s R 35E

FOOTAGE 200 ~~N/S~~ 1650 E KW

IS A FLARE STACK PRESENT? ☒ YES ☐ NO

IS FLARE ACTIVE? ☒ YES ☐ NO

IS GAS TO FLARE METERED? ☒ YES ☐ NO

AREA AROUND FLARE CLEARED? ☒ YES ☒ NO

COMMENTS: Could cut weeds around  
flare

IS VRU PRESENT? YES ☒ NO

IS VRU ACTIVE? YES ☐ NO

COMMENTS: Combuster is being used on  
tank vapors.

INSPECTOR Gary Robinson DATE 2-12-18