

FLARE INSPECTION

EOG Y

LEASE OR FACILITY NAME: DEAN APO Fod #
WELL# API#30- <u>025</u> - <u>33656</u>
U.L SEC T R R
FOOTAGE 2310 NS 2310 (E) W
IS A FLARE STACK PRESENT? YES NO
IS FLARE ACTIVE? YES NO
IS GAS TO FLARE METERED? YES NO
AREA AROUND FLARE CLEARED? YES NO
COMMENTS: Frod gas going to soles
IS VRU PRESENT? YES NO
IS VRU ACTIVE? YES NO
COMMENTS: Tank vapous are vented
INSPECTOR Say Rolenson DATE 2-23-18