District 1
1625 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (525) 3 3

## State of New Mexico

MAR 262	Oil Co	Ainerals and Natural nservation Division H	_			
-CE	VED	BRADENHEAD TE	ST REPORT			
Oil Conservation Division Hobbs District  BRADENHEAD TEST REPORT  Operator Name  VACUUM GLORIETA WEST UNIT				30 025 0 11 2 0		
Property Name				30-025- 2   4   3 2 Well No.		
Chevron USA					CelH	
		7. Surface Locati				
A 36 175 34E		Feet from La La C		ect From E/W Line	LEA	
		Well Status				
Well Status  ACTIVE  NO  PRODUCING  PRODUCING			1 /	TE /2018		
ACTIVE	A DENHEAD AND INT	ERMEDIATE TO ATMOSPHE				
OPEN BE	CADENHEAD AND INT	OBSERVED DA		CIS MINUTES EACH		
If bradenhead flowed water, o		ns that apply:				
Pressure	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing	
Flow Characteristics	0	40	NA	40	250	
Puff	VA)	Y/®	Y/N	Y/N		
Steady Flow	V/60	Ø/ N/	Y / N	Y / N	-	
Surges	YO	Y Ø	Y / N	Y / N	_	
Down to nothing	6/ N	(Y) N	Y/N	Y/N		
Gas or Oil	Y/N	7/0	Y / N	Y / N		
Water	Y/N	YN	Y / N	Y / N		
If bradenhead flowed water, c	heck all of the descriptio	ns that apply:				
CLEAR	FRESH	SALTY	SULFUR	BLAC	K	
Int blow	2 min thru/	2" did not blow	down - put	TME WTR, 9909e in.	hed 40 pst	
Int blow 2 min thru 2" did not blow down - put 9 que in, had 40 pst blow another 3 min, it went to zero.						
	-					
Signature:				OIL CONSERVATION DIVISION		
Printed name: Ruben Rodriguez				Entered into RBDMS		
Title: FIELD SPECIALIST				Re-test		
E-mail Address: TZCL@CHEVRON.COM				$\forall y$	V	
Date: 3/7/2018		15-513/5526				
0//	Witness	be Office				