District I Id25 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720 State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office BRADENHEAD TEST REPORT Operator Name Chevron USA Inc. Property Name Well No.									
Operator Name					³ API Numbe	er			
Chevron USA Inc.						32018	-		
					Well No.				
7. Surface Location UL - Lot Section Township Range Feet from N/S Line Feet From E/W Line									
	85 35E	860		2000	E	LEA	-		
Well Status									
Well Status ACTIVE	SHUT-IN		3	DATE -2/-18 V EOR 15 MINUTE	SEACH		-		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH OBSERVED DATA If bradenhead flowed water, check all of the descriptions that apply:									
	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod	Csng	(E)Tubing			
Pressure Flow Characteristics	0	NA	NA	3	D	580	-		
Puff	Ŵ/N	Y/N	Y/N		Y/N	-			
Steady Flow	Y Q	Y / N	Y / N		Y/N	-			
Surges	Y/N	Y/N	Y / N		Y/N	-			
Down to nothing	Y N	Y/N	Y / N		Y/N	-			
Gas or Oil	Y G	Y / N	Y/N		Y/N	-			
Water	Y/N	Y / N	Y / N		Y/N	-			
If bradenhead flowed water, check all of the descriptions that apply:									
CLEAR	FRESH	SALTY	SULFU	JR	BLACK				
Remarks:			INJECTING AT	THIS TIME	WTR,0	GAS,CO2			

Signature:	-	OIL CONSERVATION DIVISION
Printed name: Tanner DeHaan		Entered into RBDMS
Title: FSA		Re-test
E-mail Address: TZYR@Chevron.com		The
Date: 3-21-18	Phone: 575-390-4449	
	Witness: Lary Kolman	