Submit One Copy To Appropriate District State of New Mexico	Form C-103
Energy Minerals and Natural Resources	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240	30-025-32640
District II 811 S. First St., Artesia, NM 88210 District III 1220 South St. Francis NR 1220	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	STATE X FEE
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Lea AQ State
PROPOSALS.) 1. Type of Well: XOil Well Gas Well Other	8. Well Number #7
2. Name of Operator	9. OGRID Number
Cimarex Energy Co. of Colorado	162683
3. Address of Operator	10. Pool name or Wildcat
600 N. Marienfeld, Suite 600, Midland TX 79705	Pearl San Andres, West
4. Well Location	W
Unit Letter <u>K</u> : <u>1650</u> feet from the <u>S</u> line and <u>1650</u> feet from the <u></u>	
Section <u>29</u> Township <u>19S</u> Range <u>35E</u> NMPM <u>County L</u> 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3756	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING DIMULTIPLE COMPL CASING/CEMEN	гјов 🗌 🖌
OTHER: 🗌 🛛 Location is re	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
I The leastion has been leveled as nearly as nearly to priginal ground contain and has	been cleared of all junk track flow lines and
The location has been leveled as nearly as possible to original ground contour and has other production equipment.	been cleared of an junk, trash, now lines and
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
 All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and	d lines have been removed from lease and well
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE Amithy Crawford	st DATE 4/10/2018
TYPE OR PRINT NAME Amithy Crawford E-MAIL: acrawford@cin	narex.com PHONE: 432-620-1909
For State Use Only	
APPROVED BY: Mahhhtitchen TITLE P.E.S.	DATE 04/19/2018