

State of New Mexico  
 Energy, Minerals and Natural Resources Department  
 Oil Conservation Division Hobbs District Office  
**AUG 06 2018**  
**WELDEN HEAD TEST REPORT**

Operator Name <b>- Apache Oil</b>	API Number <b>30-025-06348</b>
Property Name <b>- Northeast Drinkard Unit</b>	Well No. <b>324</b>

Surface Location									
UL - Lot <b>0</b>	Section <b>2</b>	Township <b>21S</b>	Range <b>37E</b>	Feet from <b>860</b>	N/S Line <b>S</b>	Feet from <b>1980</b>	E/W Line <b>E</b>	County <b>Lea</b>	

Well Status										
YES	TA'D WELL <b>(NO)</b>	YES	SHUT-IN <b>(NO)</b>	<b>(INT)</b>	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE <b>5/14/18</b>

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csing	(E)Tubing
Pressure	$\emptyset$	$\emptyset$	—	0	1175
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Water level if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Tracy Cole</i>	OIL CONSERVATION DIVISION
Printed name: <b>Tracy Cole</b>	Entered into RBDMS
Title: <b>Pumper III</b>	Re-test
E-mail Address: <b>Tracy.Cole@apachecorp.com</b>	
Date: <b>5/14/18</b> Phone: <b>575-441-5196</b>	
Witness:	