



**PHOENIX**  
**TECHNOLOGY SERVICES**

August 13, 2018

**HOBBS OCD**

AUG 29 2018

RECEIVED

Oil Conservation Division  
State of New Mexico  
1625 N. French Drive  
Hobbs, New Mexico 88240

Dear District 1 - Hobbs

Re: Kaiser Francis  
Bell Lake Unit South 430H  
Lea County, NM  
API #30-025-44619  
Job No. 63046

Enclosed please find the Survey Data Certification, and the original Plat and one copy of the Survey Report performed on the above referenced well by Phoenix Technology Services, Inc. Other information required by your office is as follows:

Name & Title of Surveyor	Drain Hole Number	Surveyed Depths		Dates Performed		Type of Survey
		From	To	Start	End	
Derek Tylka	430H	1,428	19,822	7/5/18	7/28/18	MWD

A certified plat on which the bottom hole location is oriented both to the surface location and to the lease lines (or unit lines in case of pooling) is attached to the survey report. If any other information is required, please contact the undersigned at the letterhead address and phone number.

Best Regards,

*Brittany Carley*

Brittany Carley  
MWD Operations Administrator- EOW