UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

FIGURE 388

Do not use the abandoned we	is form for proposals to drill II. Use form 3160-3 (APD) fo	or to re-entered or such proposals	G Indian, Allottee	or Tribe Name
SUBMIT IN	TRIPLICATE - Other instruct	ions on page 2	2 5 2018 7. If Unit or CA/Agr	eement, Name and/or No.
1. Type of Well		•	8 Well Name and No	5 B3BO FED COM 1H
	Contact: JAC	KIE LATHAN 🛚 🗫 🖰	PRONGHORN 1  9. API Well No.	
MEWBOURNE OIL COMPAN			30-025-43903-	
3a. Address P O BOX 5270 HOBBS, NM 88241	Ph	Phone No. (include area code) : 575-393-5905	ANTELOPE RI	DGE-BONE SPRING, W
4. Location of Well (Footage, Sec., T			11. County or Parish	
Sec 15 T23S R34E NWNE 18 32.311367 N Lat, 103.454910			LEA COUNTY	NM
12. CHECK THE AI	PPROPRIATE BOX(ES) TO	INDICATE NATURE O	F NOTICE, REPORT, OR OT	HER DATA
TYPE OF SUBMISSION		ТҮРЕ О	FACTION	
☐ Notice of Intent	☐ Acidize	☐ Deepen	Production (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity
Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recomplete	☑ Other Well Spud
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug and Abandon ☐ Plug Back	☐ Temporarily Abandon ☐ Water Disposal	·· on opac
determined that the site is ready for f 08/28/18 Spud 17 1/2" hole @ 1780'. R Thixotropic w/additives. Mixed @ 13.5#/g w/1.73 yd. Tail w/2 bbls of FW. Plug down @ 12:: Annular to 3500#. At 2:30 P.M Drilled out with 12 1/4" bit. Charts & Schematic attached.	inal inspection.  an 1768' of 13 3/8" 54,5# J55  an 1768' of 13 3/8" 54,5# J55  an 14.4#/g w/1.54 yd. 2nd lea  00 sks Class C w/1% CaCl2. I  30 PM 08/30/18. Circ 279 sks  1. 08/31/18, tested csg to 1500	ST&C Csg. Cemented wad w/1250 sks Class C w/Mixed @ 14.8 #/g w/1.34 of cmt to the pits. Test B0	yd. Displaced w/266 DPE to 5000# &	·
14. I hereby certify that the foregoing is	Electronic Submission #4341 For MEWBOURNE	EOIL COMPÁNY, sent to ti	he Hobbs	
	nmitted to AFMSS for processin CABALLERO	Title REGUL	•	···
Signature (Electronic S	Submission)	Date 09/06/2	018	
- Carrier Carr	<del></del>	EDERAL OR STATE		<u></u>
			TED FOR RECORD	
_Approved By		AUUEF	TED FOR RECORD	Date
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	uitable title to those rights in the subje	varrant or ect lease Office	SEP 1 3 2018 /s/ Jona	thon She
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime statements or representations as to an	e for any person knowingly and y matter within its jurisdiction.	willfully to make to any department of	r agency of the United
(Instructions on page 2)	ISED ** BLM REVISED **	CAF	RISBAD FIELD OFFICE I REVISED ** BLM REVISE	:D** // 1/2

## Additional data for EC transaction #434113 that would not fit on the form

## 32. Additional remarks, continued

Bond on file: NM1693 nationwide & NMB000919



Billing Phone: 575-396-0255

Tielest H.	Dat			Commons	· · · · · · · · · · · · · · · · · · ·	<del></del>
Ticket #: B907	74 Dat	e: 8/30/	18	Company:	Me	wbourbe
Lease Name:  Promption I B County and State	380 Fed	com 1H		Rig#: Pa	tter	son 250
<b>County and Stat</b>	te:	<u> </u>		Time In:	T	ime Out:
Lea couri				10.00 pm		6:00 Am
Crew:	1	/ * * * * * * * * * * * * * * * * * * *				<u> </u>
180000000000000000000000000000000000000						
Description:						Total
		(1)				
<b>BOP Tester to Loca</b>	tion to tes	t ///		BOP.	<b>.</b>	
						<u> </u>
hrs @ S hrs @ S mileage for mel	120.00 pe	our for assis per mile job	stant	tester		0440 (ASS)
					<del></del>	Sub-Total
Lease Name:						144000
		'				1970
Plant Code:		CO Cod	e:			
WBS:		CAI:				Tax
Date: 8/	30/18					79.20
						Grand Total
						1519.20
Signature:						

## Man Welding Services Inc. BOP TEST SHEET

OMTE THE	8/30/18 PIG CONTRAC	PO VARIOUS TAXABLE PAR	Patters	son 250	
<b>POM</b>				B90774	
CHEVE	IN REP	STREET, STREET	<i>i</i>	<u> </u>	
Test #	Components Tested	Minutes Held (Low/High)	Low PSI	High PSI	Pass Fail
	Truck Test				2
43	annuly inside 2" inside 4"	1040	20	350	Pasy
73	TED PIPE NEWS inside It inside Y	10-60	210	5000	PUSS
49	The Pive orkide 2" article 44 HCR	low	200	500V	PLSS
# T	TOP Pite Rams crown who inside				
	velves on months outside 2"	10-60	200	500)	PLS
He	Bottom PARE nonz - 7" W/zit	10-10	20	2000	Acs
47	Back to Purps, Mand I Pup	10-60	200		PESS
K8	part value	10-60	200	5000	ous
49	T:W vive	10-W	20	500V	pus
	Blind Roms, article 4", Check une		210	5000	Desy
uu du.	Blitch Nams, Chokes, outside 44	15-W	765T 210	5000	DUS
			·		
	estable for a 1700 an along				
42	STATEL TOSTING Q. 1200 Am DIVO Was				
42	not holding had to pulland beset				
	not holding had to pull and deset				
#3	not holding had to pull and deser LOV & 12.35-12.45 High & 17.47-12.67 104/8 1:00-1:10 High 1:72-1 22 Him				
#3 14.	NOT NOIDING WAD TO PULL AND DESOT LOW D 12.35-12:45 HIGH 012:47-12:57 104/01:00-1:10 HIGH 1:72-1:22 HM 104/1:25-135-High 1:37-1:47 AM				
43 14 US	not holding had to pull and desor LOV @ 12.35-12.45 High @ 12.47-12.57 DU/ @ 1:00-1:10 High 1:72-1:22 pm DU/ 1:25-135-High 1:37-1:47 pm LOW -1:53-2:03 Hum 2:04-2:14				
43 14 15 46	NOT MOIDING WAD TO PULL AND DESET LOV D 12.35-12:45 HIGH D 12:47-12:67 104/0 1:00-1:10 HIGH 1:72-1:22 HIM LOW 1:35-135-High 1:37-1:47 AND LOW 1:53-2:03 HIM 2:04-2:14 100 2:53-2:25 HIGH 2:26-236				
43 14 15 46	NOT NOIGH WAG TO PULL AND DESCT ON 0 12:35-12:45 High 0.12:47-12:57 104/0 1:00-1:10 High 1:72-1:22 Him 104/1:35-135-High 1:37-1:47 AND 104/1:35-2:03 High 2:04-2:14 104/1:55-2:05 High 2:26-236 104-3:04-3:14-12:64 3:18-328				
43 14 15 46 47	NOT NOIGH WAG TO PULL AND DESOT OU D 12.35-12:45 High 0.12:47-12:67 104/0 1:00-1:10 High 1:72-1:22 Him 104/1:35-135-High 1:37-1:47 AND 104-1:53-2:03 High 2:04-2:14 104-1:53-2:25 High 2:26-236 104-3:04-3:14-12:64 3:18-328 104-3:30-240 Ligh 3:41-3:51				
73 14 14 14 16 17 18	NOT NOIGH WAG TO PULL AND DESOT OU D 12.35-12:45 HIGH 0.12:47-12:67 104/0 1:00-1:10 HIGH 1:72-1:22 HM 104/1:35-135-High 1:37-1:47 AND 104/1:35-2:03 HM 2:04-2:14 104-13:5-2:25 HIGH 2:26-236 104-3:04-3:14-12:64 3:18-328 104-3:30-240 Ligh 3:41-3:51 104-352-408-17:408-418				
43 14 15 46	NOT NOIGH NAME TO PULL AND TEST OUT DIST. 12:45 HIGH 012:47-12:57 DUND 1:00-1:10 HIGH 1:72-1:22 AM DUND 1:35-1:47 AM DUND 1:35-1:47 AM DUND 1:35-2:03 HIGH 2:04-2:14 LOW 1:53-2:05 HIGH 2:04-2:14 LOW 3:34-3:28 HIGH 3:18-328 LOW 3:34-2:40 HIGH 3:18-328 LOW 3:34-2:40 HIGH 3:41-3:57 LOW 3:52-408-HIGH 2:48-418 LOW 4:23-433-4:35,-448				
13 14 15 16 127 18 189 140	NOT NOIGH WAG TO PULL AND DESOT OU D 12.35-12:45 HIGH 0.12:47-12:67 104/0 1:00-1:10 HIGH 1:72-1:22 HM 104/1:35-135-High 1:37-1:47 AND 104/1:35-2:03 HM 2:04-2:14 104-13:5-2:25 HIGH 2:26-236 104-3:04-3:14-12:64 3:18-328 104-3:30-240 Ligh 3:41-3:51 104-352-408-17:408-418				
73 14 15 16 17 18 19 19 10 10	NOT NOIGH NAME TO PULL AND TEST OUT DIST. 12:45 HIGH 012:47-12:57 DUND 1:00-1:10 HIGH 1:72-1:22 AM DUND 1:35-1:47 AM DUND 1:35-1:47 AM DUND 1:35-2:03 HIGH 2:04-2:14 LOW 1:53-2:05 HIGH 2:04-2:14 LOW 3:34-3:28 HIGH 3:18-328 LOW 3:34-2:40 HIGH 3:18-328 LOW 3:34-2:40 HIGH 3:41-3:57 LOW 3:52-408-HIGH 2:48-418 LOW 4:23-433-4:35,-448				







