State Of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Govenor Sarah Cottrell Propst Cabinet Secretary Vacant Deputy Cabinet Secretary

Gabriel Wade Division Director

"Response Required - Deadline Enclosed"



Field Inspection Program "Preserving the Integrity of Our Environment"

09-Jan-19

TAP ROCK OPERATING, LLC 602 Park Point Drive Suite 200 Golden, CO 80401

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-025-34623] JACKSON UNIT SWD #006 OGRID: 372043 H-21-24S-33E 1649 FNL 657 FEL **Type Inspection Inspection Date** Inspector **Corrective Action Due By Inspection No.** 12/11/2018 **Routine Inspection** [GR] Gary Robinson 3/11/2019 iGR1834534764 Violations: Rule Violation Comment 19.15 Oil and Gas Mechanical Integrity Failure Recorded MIT failure was added

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely, Havy Robinson

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

Oil Conservation Division * 1625 N. French Drive * Hobbs, NM 88240 Phone: 575-393-6161 * Fax: 575-393-0720 * www.emrd.state.nm.us **LETTER OF VIOLATION - Other**

HOBBS OCD

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

RECEIVED

1

DEC 1 1 2018

BRADENHEAD TEST REPORT APINumber Operator Nanie 30-025-34623 Dorating Property Name # JACKSON 0 ¹ Surface Location Feet from Township N/S Line Feet From E/W Line UL - Lot Section Range County 3.3E 457 1649 245 EA 2 F Well Status INJECTOR TA'D WELL SHUT-IN PRODUCER DATE NO NO) SWD 12-11-1 YES INJ OIL GAS YES

OBSERVED DATA

	(A)Surface	(B)Interni(I)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	MA	NA	1100	500
Flow Characteristics					
Pull	10	Y/N	Y / N	Y/O	- CO2
Stendy Flow	I Ø	Y / N	Y / N	0	GAS
Surges	YIO	Y / N	Y / N	1C	- GAS
Down to nothing	0	Y / N	Y / N	10	Injected for
Gas or Oil	Y O	Y E N	Y / N	1 O	
Water	10	Y/ N	Y / N	T N	

Remarks - Please state for each string (A.B.C.D.E) perment information regarding bleed down or continuous build up if applies.

Prod. CSg. would not blow down.

Well was shut in. failed. BaltT

Signature: Agus	h h n m	OIL CONSERVATION DIVISIO		
Printed name: GARA	Juhnon	Entered into RBDMS		
Title:		Re-test		
E-mail Address:				
Date:	Phone:			
	Witness: Saugholanson			

INSTRUCTIONS ON BACK OF THIS FORM

EMNRD OIL CONSERVATION DIVISION 1625 N FRENCH DRIVE HOBBS NM 88240



TAP ROCK OPERATING, LLC 602 PARK POINT DRIVE SUITE 200 GOLDEN, CO 80401