Submit One Copy To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240 District II OH. CONSERVATION DIVISION	$\int_{\Omega} \int_{\Omega} \mathcal{V}^{(1)}$ Form C-103
District 1 Energy, Minerals and Natural Resources	Revised November 3, 2011 WELL APPNO.
1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St. Artesia NM 88210 OIL CONSERVATION DIVISION	30-025-03798
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	o. State on a das Boase 110.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	LOVINGTON PADDOCK UNIT 8. Well Number
PROPOSALS.) 1. Type of Well: Gas Well Other	016
2 Name of Operator	9. OGRID Number
Chevron USA Inc. M. dcontinent, LP 3. Address of Operator	241333 10. Pool name or Wildcat
6301 Deauville Blvd., Midland, TX 79706	LOVINGTON PADDOCK
4. Well Location:	
Unit Letter_D:660_feet from the NORTH line and 660_feet from the WEST_line	
Section 36 Township 16-S Range 36-E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3,854' DF	A State and the
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	<u> </u>
TEMPORARILY ABANDON	RILLING OPNS. P AND A
	_ 14
OTHER:	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMAT PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	ION HAS BEEN WELDED OR
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.) All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
Note: All Chevron equipment has been removed. Poured in place pump jack pad remains. When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
When all work has over completely, retain the course of appropriate District Course of Course and State Course	
SIGNATURE Katherine Papageorge TITLE Decommissionin	g Project ManagerDATE2.25.19
TYPE OR PRINT NAMEKatherine Papageorge_E-MAIL: _Katherine.Papageorge@chevron.com PHONE:832-854-5291 For State Use Only	
APPROVED BY: Kerry Forthe TITLE Compliance	Officer A DATE 2-26-19