## **HOBBS OCD**

District | 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

Well Status

MAY 01 2019

RECEIVED

## State of New Mexico **Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office BRADENHEAD TEST REPORT**

Operator Name Cross Timber Energy, LLC						<sup>3</sup> API Number 3002523873		
Property Name North Vacuum ABO East Unit							Well No. 6	
				<sup>7.</sup> Surface Location		<u> </u>		
UL - Lot D	Section 18	Township 17S	Range 35E	Feet from 660	N/S Line FNL	Feet From 660	E/W Line FWL	County Lea
				Well Status				
Well	Status	ł	SHUT-IN	PRODUCING		DATE		

4-9-2019 NO OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**OBSERVED DATA** 

## If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	0			0	4125
Flow Characteristics					
Puff	Y / 🕥	Y/N	Y / N	Y / 🕅	1
Steady Flow	Y I O	Y / N	Y / N	Y / 🕅	1
Surges	Ÿ/O	Y / N	Y/N	Y / Ø	1
Down to nothing	Y / O	Y/N	Y / N	Y / 🔞	1
Gas or Oil	Y / 🕑	Y / N	Y/N	Y /	1
Water	Y / (Ň)	Y / N	Y/N	Y / O	]

## If bradenhead flowed water, check all of the descriptions that apply:

			· · · · · · · · · · · · · · · · · · ·	
CLEAR		SALTY	SULFUR	BLACK
	· · · · · · · · · · · · · · · · · · ·			

Remarks:	INJECTING AT THIS TIME WTR, GAS,CO2

Signature:		OIL CONSERVATION DIVISION	OIL CONSERVATION DIVISION			
Printed name:		Entered into RBDMS	1			
Title:		Re-test	_			
E-mail Address:		17				
Date:	Phone:					
	Witness:					