## **HOBBS OCD**

## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

MAY **01** 2019

## **BRADENHEAD TEST REPORT**

RECEIVED

			Operato	r Name		30 1 103		<del>- 1</del>		API Numbe		
CROSS TIMBERS ENERGY, LLC									30-025-28724			
NORTH VACUUM ABO UNIT									Well No. 254			
		·	· · ·		7. Surface Loca	tion					<del></del>	
		Township			Feet from				n E/W Line		County	
	13	17S	34E	<u> </u>	1980 Well Statu		FSL	746		FEL	LEA	
							· · · · · · · · · · · · · · · · · · ·					
Well Status			SHUT-IN		PRODUCINO		4-9-		18			
L	OPF	N RRADEN		TERMEN	IATE TO ATMOSPH	EDE INDI				FACU		
	OLE	IN BRADEN	HEAD AND IN	LENVIED	OBSERVED DA		VIDUALL	1 FOR 15 MIN	UIES	EACH		
<u>If bradenhead</u>	flowed wa	ter, check all	of the descripti	ions that a	oply:	AIA						
		(A)Si	(A)Surf-Interm		(B)Interm(1)-Interm(2)		(C)Interm-Prod		(D)Prod Csng		(E)Tubing	
Pressure			0						30		25	
Flow Characteristics												
Puff			V/Ø		Y / N		Y/N		Y/N		]	
Steady Flow Surges			Y/89		Y/N Y/N	Y/N Y/N			Y/N			
Down to nothing			Y / 8)		Y/N	Y/N			Y/N Y/N		-	
Gas or Oil			Y / (S)	<del>                                     </del>	Y / N	Y/N			Y/N		-	
Water			Y / (N)		Y / N		Y/N		Y / N			
		<u>l</u>		1				L	-	·	J	
f bradenhead flowed water, check all of the descriptions that apply:												
CLEAR		FRE	FRESH		SALTY		SULFUR		BLACK			
Remarks:						INJECT	TING AT 1	HIS TIME	W	rr, (	GAS, CO2	
							·					
	4							· · · · · · · · · · · · · · · · · · ·				
Signature: Lasa								OIL CONSERVATION DIVISION				
Printed name: TOSE CASAS								Entered into RBDMS				
Title: IPAR Ornata								Re-test				
E-mail Address: TCASAS @ Ct Fields us, lom												
Date: 4-5-2017 Phone: 575-746-7220									,			
	Witness:							<del></del>				