

	oC'	Ø
	of Nethorn 10's 10's and Natural Repources	9
Submit One Copy To Appropriate District Office State o	f Ne Mexico	Form C-103 Revised November 3, 2011
District I Energy, IMmeral 1625 N. French Dr., Hobbs, NM 88240	S and Natural Repources VATION DIVIOUS th St. France	WELL API NO.
District II 811 S. First St., Artesia, NM 88210 OIL CONSER	VATION DIVIDON	30-025-02275 5. Indicate Type of Lease
Conto	th St. Francis 97. Fe, NM 87505	31112
1220 S. St. Francis Dr., Santa Fe, NM	, c, 14141 87303	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		VACUUM GRAYBURG SAN ANDRES UNIT
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number
2. Name of Operator		9. OGRID Number
Chevron U.S.A Inc.		4323
3. Address of Operator 6301 Deauville Blvd., Midland, TX 79706		10. Pool name or Wildcat VACUUM; GRAYBURG-SAN ANDRES
4. Well Location:		
Unit Letter_O_:660_feet from the <u>SOUTH</u> line and <u>1980</u> feet from the <u>EAST</u> line		
Section 02 Township 18-S Range 34-E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
4,007' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
OTHER: Location is ready for OCD inspection after P&A		
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
 ☑ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. 		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)		
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE Katherine Papageorge TITLE Decommissioning Project Manager DATE 8.26.19		
TYPE OR PRINT NAMEKatherine Papageorge_E-MAIL: _Katherine.Papageorge@chevron.com PHONE:832-854-5291 For State Use Only APPROVED BY: KICK OF AN TITLE A DATE 8: 26-19		
APPROVED BY KICK KICK MAN	TITLE H	1 DATE 8-26-19