

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.***Carlsbad Field Office**
OCD HobbsSerial No.
NMNM66925

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other Instructions on page 2

HOBBS OCD

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

AUG 22 2019

2. Name of Operator
OXY USA INCORPORATEDContact: SARAH E CHAPMAN
E-Mail: SARAH_CHAPMAN@OXY.COM8. Well Name and No.
MESA VERDE WC UNIT 5H9. API Well No.
30-025-45862-00-X13a. Address
P O BOX 4294
HOUSTON, TX 77210-42943b. Phone No. (include area code)
Ph: 713-350-499710. Field and Pool or Exploratory Area
MESA VERDE

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 17 T24S R32E SESW 280FSL 2436FWL
32.210983 N Lat, 103.697411 W Lon

11. County or Parish, State

LEA COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Drilling Operations
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

6/16/19 MIRU, test BOP to 5000# high 250# low, good test. Test 10-3/4" csg to 1500# for 30 minutes, good test. RIH & drill new formation to 988', perform FIT test to EMW=8.5ppg 488#, good test. Drill 9-7/8" hole to 11577'. RIH & set 7-5/8" 26.4 HCL-80 BTC csg @ 11567', pump 80bbl MPE spacer then cmt w/ 823sxs (289bbl) class H w/ additives 12.8ppg 1.97 yield followed by 636sxs (182bbl) class H w/ additives 13.2ppg 1.61 yield. Full returns throughout job but no cmt to surface. Notified BLM of plan forward. Pump 331sxs (116bbl) class H w/ additives 12.8ppg 1.96 yield, followed by 909sxs (285bbl) class H w/ additives 12.8ppg 1.76 yield. No cmt to surface. Pump 127sxs (40bbl) class H w/ additives 12.8ppg 1.76 yield, no cmt to surface, WOC. Pump 64sxs (20bbl) class H w/ additives 12.8ppg 1.76 yield, no cmt to surface, WOC. Pump 32sxs (10bbl) class H w/ additives 12.8ppg 1.76 yield, circ cmt to surface. Spoke with Mandela at BLM on 6/25/19. Noticed plug not holding pressure so ran in with cmt retainer to a depth of 11523', performed cmt shoe squeeze w/ 772sxs (220bbl) class H w/ additives 13.2ppg 1.6 yield. Annulus took 294sxs (84bbl), performed sting out

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #474902 verified by the BLM Well Information System
For OXY USA INCORPORATED, sent to the Hobbs

Committed to AFMSS for processing by TANJA BACA on 07/25/2019 (19TAB0015SE)

Name (Printed/Typed) SARAH E CHAPMAN

Title REGULATORY SPECIALIST

Signature (Electronic Submission)

Date 07/24/2019

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Accepted for Record

JUL 31 2019

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Jonathon Shepard
Carlsbad Field Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #474902 that would not fit on the form

32. Additional remarks, continued

of retainer and circ excess cmt to surface (477sxs). 6/28/19 Notified BLM of job status and intent to RD & RR.