Submit One Copy To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II	, ,	OVELL API NO 30-025-45692
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. France Pr	STATE A FEE
District IV	Santa Fe, NM 87505 SEP 2 5 20	No 0. Blate on de Gus Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	02 - 51	VED /
1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BARE TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name SAVAGE 2 STATE COM
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other		8. Well Number #505
2. Name of Operator		9. OGRID Number
EOG RESOURCES, INC		7377
3. Address of Operator PO BOX 2267 MIDLAND, TEXAS 79702		10. Pool name or Wildcat WC025 G07 S243225C; LWR BONE SPRING
4. Well Location		
Unit Letter B_: <u>403</u> feet from the NORTH line and <u>3108</u> feet from the <u>WEST</u> line		
Section <u>02</u> Township <u>25S</u> Range <u>32E</u> NMPM <u>County LEA</u>		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3529' GL		
12. Check Appropriate Box to Indi	cate Nature of Notice, Report or Other	
		BSEQUENT REPORT OF:
	G AND ABANDON C REMEDIAL WO	
PULL OR ALTER CASING 🛛 MUL	TIPLE COMPL	
OTHER:	□ ⊠ Location is	ready for OCD inspection after P&A
<ul> <li>All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.</li> <li>Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.</li> <li>A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the</li> </ul>		
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> <u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u>		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastructure.		
When all work has been completed, return LOST THIS WELLBORE – REDRILLED #505Y – A	this form to the appropriate District office to so	chedule an inspection.
signature Kung Mudulu F	TITLE: REGULATORY S	PECIALIST DATE 09/23/2019
TYPE OR PRINT NAME: KAY MADE For State Use Only	OOX E-MAIL: <u>kay_maddox@eogresource</u>	<u>s.com</u> PHONE: _432-686-3658 م
APPROVED BY: King Firt	en TITLE C. Oi	DATE 10-10-19
Conditions of Approval (if and):		
		N.

.