Submit One Copy To Appropriate District Office	State of New Mexico		Form C-103	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised November 3, 2011 WELL API NO.	
District II 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-26853	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE	
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name QUAIL QUEEN UNIT	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			8. Well Number	
PROPOSALS.) 1. Type of Well: ⊠Oil Well □	Gas Well Other	acD	6	iniber
2. Name of Operator	Gas Well Other HOBBS OCD 179706 JAN 0 3 2020		9. OGRID Number	
CHEVRON USA, INC. 3. Address of Operator	HOD		4323 10. Pool name or Wildcat	
6301 Deauville Blvd., Midland, TX	79706 IAN	0 3 2020		EEN; SWD, SAN ANDRES
		-NED		, ,
4. Well Location: Unit Letter_N : 660 feet from the SOUTH line and 1980 F. Gen the WEST line Section 11 Township 19-S Range 34-E NMPM County LEA				
	11. Elevation (Show whether DR) 3,988' GL	RKB, RT, GR, etc.)		•
12. Check Appropriate Box to		eport or Other Da	ata	10.00.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
	PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			□ ALTERING CASING □
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRIL		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB	
OTHER:	П	│	adv for OCD	inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR </u>				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.) All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well				
location, except for utility's distribution infrastructure.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE Katherine Papageorge TITLE Decommissioning Project Manager DATE 12.29.19				
TYPE OR PRINT NAMEKatherine Papageorge_E-MAIL: _Katherine.Papageorge@chevron.com PHONE:832-854-5291 For State Use Only				
APPROVED BY: Xerry First TITLE () A DATE 1-6-20				