HOBBS OCD

APR 1.6 2020

Submit One Copy To Appropriate District Office	State of New M	exico		Form C-103
District I Energy, Minerals and Natural Resource Revised November 3, 2011				
1625 N. French Dr., Hobbs, NM 88240 District II			30-025-102	
811 S. First St., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate T	
1000 Rio Brazos Rd., Aztec, NM 87410	NM 87410 Santa Fe, NM 87505		STAT	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil d	& Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS				ne or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well Gas Well Other			7	
2. Name of Operator Chevron USA Inc.			9. OGRID Number 4323	
3. Address of Operator			10. Pool name or Wildcat	
6301 Deauville Blvd., Midland, TX 79705			BLINEBERRY OIL & GAS	
4. Well Location:				
Unit Letter C: 660 feet from the NORTH line and 2310 feet from the WEST line				
Section 14 Township 22-S Range 37-E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
	GR 3356'	t, кк <i>b</i> , к1, Gк, еіс.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐ I			
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OPNS. P AND A			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	T JOB L	_
OTHER: Discretion Location is ready for OCD inspection after P&A				
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR </u>				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The best of the best book as well as well as well as well as well as well as the best book as the best book as				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.) All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines.				
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.				
tocation, except for utility's distribution infrastructure.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE Katherine Papageorge TITLE Decommissioning Project Manager DATE 4.7.2020				
TYPE OR PRINT NAMEKatherine Papageorge E-MAIL: _Katherine.Papageorge@chevron.com PHONE:832-854-5291 For State Use Only APPROVED BY:				
\longrightarrow	1 A	(//	A	417-21
APPROVED BY: / 4/1/09	TITLE_		1	DATE / \ / / / /