Hobbs ocd

Submit One Copy To Appropriate District Office	State of New Me	exico Mara	• •	Form C-103
District I	Energy, Minerals and Natu	ral Resources 47	2 7 2020	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II			WELLAII	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISIONE C	5/1/5:53	Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Hallels D1.		STA	
District IV	Santa Fe, NM 8/505			& Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
- · · · ·	ES AND REPORTS ON WELLS		7. Lease N	ame or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			HUGH COI	
PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well Gas Well Other			16 Y	
2. Name of Operator Chevron USA Inc.			9. OGRID 4323	Number
3. Address of Operator			10. Pool name or Wildcat	
6301 Deauville Blvd., Midland, TX 79705			PENROSE SKELLY, GRAYBURG	
4. Well Location:				
Unit Letter E: 1650 feet from the NORTH line and 965 feet from the WEST line				
Section 14 Township 22-S Range 37-E NMPM County LEA				
	11. Elevation (Show whether DR,			
<u> </u>	3361' GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INT	ENTION TO:	SUB	SEQUENT	REPORT OF:
	PLUG AND ABANDON	REMEDIAL WORK		☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRII	LLING OPNS	. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB	
OTHER:		⊠ Location is re	ady for OCD	inenection after P&A
OTHER:				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR				
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)				
All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been	abandoned in accordance with 1	9.15.35.10 NMAC.	All fluids ha	we been removed from non-
retrieved flow lines and pipelines.  If this is a one-well lease or last re	maining well on lease: all electri	cal service notes and	l lines have h	een removed from lease and well
location, except for utility's distribution		car service poies and	i illies liave o	cen removed from lease and wen
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE Katherine Pap	<u>rageorge</u> TITLE_	Decommissioning I	Project Mana	gerDATE5.15.2020
SIGNATURE <u>Katherine Papageorge</u> TITLE Decommissioning Project Manager DATE 5.15.2020				
TYPE OR PRINT NAMEKatherine Papageorge_E-MAIL: _Katherine.Papageorge@chevron.com PHONE:832-854-5291 For State Use Only				
· · · · · · · · · · · · · · · · · · ·				
APPROVED BY:	TITLE	()	$\sqcap$	DATE 5-26-26