

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company YATES PETROLEUM CORPORATION	OGRID Number 25575	Contact SHERRY BONHAM
Address 105 S 4 TH STREET		Telephone No. 505.748.1471
Facility Name ROSEMARY BOOSTER PUMP	API Number 3002 531227	Facility Type PIPELINE

Surface Owner FEDERAL	Mineral Owner FEDERAL	Lease No.
--------------------------	--------------------------	-----------

LOCATION OF RELEASE

Unit Letter L	Section 6	Township 22S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude _____ Longitude _____

WTR 2001

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 100 B/PW and 1/2 B/O	Volume Recovered 12 Barrels PW/O
Source of Release PIPELINE	Date and Hour of Occurrence 08/09/07 5:00 AM	Date and Hour of Discovery 08/09/07 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? PAT RICHARDS	
By Whom? ROBERT ASHER	Date and Hour 8/9/07 9:25 AM AND FOLLOW UP EMAIL 8/10/07 9:45 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

CHLORIDES ?

Describe Cause of Problem and Remedial Action Taken.*

ELECTRICAL PROBLEM CAUSED CONNECTIONS ON WATER LINE TO MELT. TURNED PUMP OFF AND SHUT VALVE ON WATER LINE. REPAIRS MADE TO LINE.

Describe Area Affected and Cleanup Action Taken.*

APPROXIMATELY 75' X 20' AREA AFFECTED. CALLED IN VACUUM TRUCK. VACUUMED STANDING FLUIDS. EXCAVATED AND HAULED IMPACTED MATERIALS TO DISPOSAL FACILITY.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION 	
Printed Name: Sherry Bonham	Approved by District Supervisor: ENVIRONMENTAL ENGINEER	
Title: Environmental Regulatory Agent	Approval Date: 9.11.07	Expiration Date: 10.12.07
E-mail Address: sheryb@ypcnm.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: August 22, 2007	Phone: 505.748.1471	

SUBMIT FINAL C-141

W/DOCUMENTATION BY

RP# 1552

* Attach Additional Sheets If Necessary