




COMPANY NAME: Oxy

SITE NAME: State 33 #2

LEGAL DESCRIPTION: UL F, Section 33, T21S, R35E

BATTERY:	N 32.43690° W 103.37406°	ELEVATION: 3662
NW WINDMILL:	N 32.44849° W 103.40575°	ELEVATION: 3632
NE WINDMILL:	N 32.44749° W 103.35913°	ELEVATION: 3602
SW WINDMILL:	N 32.41626° W 103.40162°	ELEVATION: 3631

**CARDINAL
LABORATORIES**

PHONE (575) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
BBC INTERNATIONAL, INC.
ATTN: CLIFF BRUNSON
P.O. BOX 805
HOBBS, NM 88241
FAX TO: (575) 397-0397


Receiving Date: 11/20/09
Reporting Date: 11/24/09
Project Owner: OXY
Project Name: STATE 33 #2
Project Location: 176


Analysis Date: 11/24/09
Sampling Date: 11/16/09 & 11/17/09
Sample Type: SOIL
Sample Condition: INTACT
Sample Received By: ML
Analyzed By: HM

LAB NUMBER SAMPLE ID		Cl ⁻ (mg/kg)
H18778-1	SP1 @ SURFACE	10,300
H18778-2	SP1 @ 2'	2,030
H18778-3	SP1 @ 3'	160
H18778-4	SP2 @ SURFACE	1,760
H18778-5	SP2 @ 2'	224
H18778-6	SP2 @ 4'	288
H18778-7	SP3 @ SURFACE	23,000
H18778-8	SP3 @ 1'	800
H18778-9	SP3 @ 4'	1,150
Quality Control		500
True Value QC		500
% Recovery		100
Relative Percent Difference		< 0.1

METHOD: Standard Methods 4500-ClB

Note: Analyses performed on 1:4 w:v aqueous extracts.
Not accredited for Chloride.


Chemist


Date 11/24/09

H18778 BBC

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



PHONE (505) 397-6388 • FAX (505) 397-0397 • 1324 W. MARLAND • P.O. BOX 805 • HOBBS, NM 88241-0805
E-MAIL cbrunson@bbcinternational.com

Groundwater Plot

Oil/Gas Well Name:

R 35E

