

M-G-F DRILLING Co., Inc.

1126 VAUGHN BUILDING

MIDLAND, TEXAS 79701

915 - MU 4-7121

INCLINATION REPORT

OPERATOR:

SPUD DATE:

LOCATION: Nine Ranch # 3
1980' FSL, 1980' FWL,
Sec. 22, T-10-S, R-33-E
Lea County, New Mexico

COMPLETED:

DEPTH FEET	ANGLE OF INCLINATION (DEGREES)	DEPTH FEET	ANGLE OF INCLINATION (DEGREES)
200	1/4	4919	1/2
370	1/4	5285	3/4
750	1/2	5775	3/4
1070	3/4	6190	1/2
1440	3/4	6440	1/2
1722	1	6745	1
2210	1/2	6993	3/4
2660	1 1/4	7343	1/2
3151	1	7699	1/2
3575	1	7910	3/4
3990	3/4	8150	1/4
4284	3/4	8595	1
4598	1/2	8830	1 1/4
		9005	1 1/4
		9130	1
		9490	1/2