## NEW MEXICO OIL CONSERVATION COMMISSION

JC 25 3

(Ray) MISCELLANEOUS REPORTS ON WELLS (Submit to appropriese Diviner Office as per Commission Rule 1706 Name of Company Address BTA Oil Producers 104 South Pecos, Midland, Teras 70701 Lease Well No. Unit Letter Section Township C.C. 691 Ltd. State D 16 9-S 35-E Date Work Performed County Mideler Aldison Denn Ext. This is a REPORT OF (Check appropriate block) 2-20 to 3-8-69 Lea Beginning Drilling Operations X Casing Test and Cement Job Other (Explain): Plugging Remedial Work Detailed account of work ione, nature and quantity of materials used, and results obtained. Now Grilling 7-7/8" hole @ 7234'. 2-20-08: Now drilling 7-7/8" hole @ 8932'. 2-26-69: Now drilling 7-7/8" hole @ 9608'. 3-3-69: Drilled 7-7/8" hole to 9850'. Ran  $5\frac{1}{2}$ " O.D. J-55 & N-80 1/# -685.13-7-69: set @ 9850' w/300 sx. cement. Plug down 3 P.M. 3-7-69. After WOC 18 hrs., pressure tested casing to 2000#, - Held  $\sim 3$ 3-8-69: Now MORT. Prep. to complete. withe ssea by Position Company Louis Theaux Field Supt.Drlq. BTA Oil Producer FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY ORIGINAL WELL DATA DF Elev. TD PBTD Producing Interval Comp.er Tubing Diameter Tubing Depth Oil String Diameter Oil String Depth Perforated interval Open Hole was was Producing Formation(s) RESULTS OF WORKOVER Jate of Oil Production Gas Production Water Production Test GOR Cas Well Potential Test BPD MCFPD BPD Cubic feet/Bbl MCFPD Before Workover After Workover I hereby certify that the information given above is true and compact to the best of my knowledge. OIL CONSERVATION COMMISSION Approved b Name Title Position Drilling Manager Dace

Company

BTA Oil Producers