

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM O-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER PXA	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name Rives
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER N 660 South 1980 THE West LINE, SECTION 4 TOWNSHIP 9-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat Vada Penn
11. Elevation (Show whether DF, RT, GR, etc.) 4279.4' GL	12. County Lea

10. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in service unit 2-22-83. Pump 100 bbls water and circulated hole. Pulled tubing to 8725' and spot 50 sx cement plug. Pulled up and WOC. Tagged cement plug at 8335'. Circulate hole with 10# brine water and salt gel. Ran freepoint and cut 5-1/2" casing at 1800'. Laid down 53 jts. of 5-1/2" casing. Ran tubing to 4020' and spotted 25 sx cement plug. Pulled up to 2940' and spotted 25 sx cement plug. Pulled up to 1850' and spotted 50 sx cement plug. Tagged cement plug at 1610'. Ran freepoint on 8-5/8" casing and cut casing at 746'. Laid down 22 joints. Ran tubing to 796' and pump 50 sx class C cement and displace cement. Pulled tubing to 365' and pump 50 sx class C cement. Displaced cement. Cut off surface head. Spot 10 sx class C cement at surface. Installed plug and abandonment marker. Moved out service unit 3-1-83.

O+5-NMOCD, H 1-HOU 1-W. Stafford, HOU 1-CMH

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <i>Charles M. Herring</i>	TITLE Assist. Admin. Analyst	DATE 3-14-83
APPROVED BY <i>David Catano</i>	TITLE OIL & GAS INSPECTOR	DATE DEC 5 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAR 18 1983
C.C.D.
HOBBS OFFICE