

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E 7067

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry	7. Unit Agreement Name
2. Name of Operator H. L. Brown, Jr.	8. Farm or Lease Name State MPC
3. Address of Operator 309 Midland Tower, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM West LINE, SECTION 10 TOWNSHIP 10 S RANGE 36 E NMPM.	10. Field and Pool, or Wildcat South Crossroads
15. Elevation (Show whether DF, RT, GR, etc.) 4019' GL	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-19-71: Depth 12,337'. Went in hole to log. Found bridge at 5860'. Went in hole, drilled out bridges. Ran drill pipe to 6500'. Circulated 3-1/2 hours. Came out of hole. Went in hole to log. Found bridge at 5730'.

3-20-71: Went in hole open ended. Set 35 sxs from 12,337' - 12,214', 35 sxs from 9425' to 9302', 25 sxs from 7740' - 7652', 25 sxs from 5590' - 5502', 25 sxs from 4150' - 4063', set 10 sxs at surface. Erected dry hole marker. Well plugged and abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **B. D. Baker** TITLE **Petroleum Engineer** DATE **April 2, 1971**

APPROVED BY **John W. Runyan** TITLE **Geologist** DATE

CONDITION OF APPROVAL, IF ANY:

RECEIVED

APR 6 1971

OIL CONSERVATION COMM.
RODERS, N. M.