

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. **LC - 064900**

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ **May 29** _____, 19 **56**

Well No. **Federal-Shellin 8-17** is located **2310** ft. from **N** line and **390** ft. from **W** line of sec. **17**

N/A Section 17 (1/4 Sec. and Sec. No.) **T-15-S** (Twp.) **R-31-E** (Range) **S.M.P.M.** (Meridian)

Cayrock Green (Field) **Chaves** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **4452** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded **May 29, 1956**.
 Drilled **11"** hole to **311'**.
 Cemented **8-5/8"** O.D., **24 1/2**, **J-55**, **300**, **3200**, new cmls. casing at **307-31'** with **175 sacks 1/2 gal cement with 2% calcium chloride added**.
 Cement circulated, waited on cement **2 1/2** hours.
 Tested casing with **1000'** for **30** minutes - O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.


Company **Union Oil Company of California**

Address **619 West Tenth Avenue**

Midland, Texas

By **R.W. Yarbrough**

Title **Drilling Dept.**



(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office
Lease No. LC - 064900
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

..... May 29 , 19 56

Well No. Factory 1-Mod 11a
8-17 is located 330 ft. from N line and 390 ft. from W line of sec. 17

17/A Section 17 T-15-G R-32-S S.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Coyne Creek Chaves New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4422 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded May 25, 1956.
Drilled 11" hole to 311'.
Cemented 8-5/8" O.D., 24-lb, J-55, 300', 3750', new cable casing at 307.31' with
175 sacks 4 1/2 gal cement with 2% calcium chloride added.
Cement circulated, waited on cement 24 hours.
Tested casing with 1000psi for 30 minutes - O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Union Oil Company of California
Address 619 West Texas Avenue
Midland, Texas
By Rud. Yarrington
Title Drilling Supt.