

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYN. M. O. G. C. COPY
SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-03844

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> WATER INJECTION WELL		7. UNIT AGREEMENT NAME ROCK QUEEN UNIT /	
2. NAME OF OPERATOR GREAT WESTERN DRILLING COMPANY		8. FARM OR LEASE NAME TRACT NO. 4	
3. ADDRESS OF OPERATOR P.O. BOX 1659 MIDLAND TX 79701		9. WELL NO. 27-2	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330'FNL & 1650'FEL, Sec. 27, T-13-S, R-31-E		10. FIELD AND POOL, OR WILDCAT CAPROCK QUEEN	
14. PERMIT NO.		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA SECTION 27	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) DF 4422'		12. COUNTY OR PARISH Chaves	
		13. STATE New Mex.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☒ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

USGS notified 24 hrs. prior to setting bottom plug.

2-26-76 RU csg pullers. Pulled inj. installation. Ran tbg & tagged bottom @ 2996'. Spotted 50 sx plug @ 2996'. Pulled tbg.

2-27-76 Ran wireline meas. & tagged plug @ 2818' (178 plug). Cut off surface pipe & welded on pull nipple. RU csg jacks. Jumped csg collar 3 jts down - screwed back into fish. Shot csg @ 694' & 632'. Pulled 21 jts 7" (628.52').

2-28-76 Ran tbg & displaced hole w/9.5#/gal br. gel mud. Spotted 35 sx plug 682-572'. Spotted 45 sx plug 357-257' & 10 sx plug @ surface w/dry hole marker.

PLUGGED AND ABANDONED 2-28-76.RECEIVED
MAR - 4 1976
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Th. Ballard

TITLE

General Superintendent

DATE

3-3-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

MAR 5 1976

D. C. C.
ARTERIA, OFFICE