

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Enserch Exploration, Inc.	8. Farm or Lease Name Lambirth
3. Address of Operator 7701 N. Stemmons Freeway, Suite 800, Dallas, Texas 75247	9. Well No. 2
4. Location of Well UNIT LETTER N 300 FEET FROM THE South LINE AND 2150 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 5 South RANGE 33 East NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4426.5' G.R.	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was spudded March 13, 1978.

13-3/8", 48#, H-40 casing was set at 361' and cemented with 350 sacks Cement March 13, 1978.

12-1/4" hole was drilled to 3520', 8-5/8" casing was set to 3492' and cemented with 2130 sacks cement March 24, 1978.

7-7/8" hole was then drilled to 4024' at which time it was discovered the surface location was in error.

Drilling operations were suspended at this time.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. P. Kinder TITLE Drilling Superintendent DATE April 4, 1978

APPROVED BY Jerry Sexton TITLE Dist. 1, Supv. DATE APR 10 1978

CONDITIONS OF APPROVAL, IF ANY