

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

### OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-30542
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-988

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>7. Lease Name or Unit Agreement Name</p> <p align="center">Victorio State</p>	
<p>1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>8. Well No.</p> <p align="center">1</p>	
<p>2. Name of Operator</p> <p>Siete Oil &amp; Gas Corporation</p>		<p>9. Pool name or Wildcat</p> <p align="center">Shipp Strawn</p>	
<p>3. Address of Operator</p> <p>P.O. Box 2523 Roswell, NM 88202-2523</p>			
<p>4. Well Location</p> <p>Unit Letter <u>L</u> : <u>1650</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line</p> <p>Section <u>31</u> Township <u>16S</u> Range <u>38E</u> NMPM <u>Lea</u> County</p>			
<p>10. Elevation (Show whether DF, RKB, RT, GR, etc.)</p> <p align="center">3741.6' GR</p>			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: _____ <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Bottomhole Survey</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Due to severe deviations of  $4\frac{3}{4}^\circ$  @ 10847' &  $4\frac{1}{2}^\circ$  @ 10892', Siete Oil & Gas Corporation plugged back from TD of 10927' to 8966' by spotting a 125 sx cement plug from 9200' to 8966' on 2/23/89, the plug was dressed to 9100', cement not firm enough, set second cement plug from 9100' to 8939'. GIH w/downhole motor to straighten wellbore, please refer to attached sub-surface directional survey report for bottomhole information.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cathy Batley TITLE Drilling & Production DATE 6/2/89

TYPE OR PRINT NAME \_\_\_\_\_ TELEPHONE NO. \_\_\_\_\_

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JUN 5 1989

CONDITIONS OF APPROVAL, IF ANY: