

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 14931

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Tonto Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

East Lusk, Bone Spring

11. SEC., T., R., M., OR B.L.E. AND
SURVEY OR AREA

Sec 27, T-19-S, R-32-E

12. COUNTY OR PARISH

Lea

13. STATE

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Sun Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 1861 Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660 FNL, 660 FWL, Sec 27, T19S, R32E U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

14. PERMIT NO.

Blanket

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

RKB 3606

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Plugback to Bone Springs ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4/27/77 MIRU - Pull Rods - Pull Tbg.

4/28/77 Set CIBP on WL @ 10500 - Perf 10131-34 w/1 JSPF 4" Welex Csg. Gun.

4/29/77 Run 2 7/8" Tbg w/5 1/2" Otis MH-2 Packer. Set Pkr. @ 10121. Spot Acid - 1000 Gal 15% CRA. Swab. Re-set Pkr. @ 10050. Test Pkr. 1000 PSI & Sqz Perfs.

4/30/77 Run 2 7/8" Tbg.-TS 4082, SN 4029, TM 3995. Run Rods w/2 1/4 Pump.

6/4/77 Tested 24 hrs. Pump 11 B0, 460 BW, 4 MCF (364 GOR)

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Office Assistant

DATE 6/16/77

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JUN 17 1977

BERNARD MOROZ
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side